

Customer Notification

EW78K-xxx-EE

**Embedded Workbench[®] for 78K
Integrated Development Environment**

Operating Precautions

EW78K-FULL-EE

EW78K-KS16-EE

EW78K-KS4-EE

DISCLAIMER

The related documents in this customer notification may include preliminary versions. However, preliminary versions may not have been marked as such.

The information in this customer notification is current as of its date of publication. The information is subject to change without notice. For actual design-in, refer to the latest publications of NEC's data sheets or data books, etc., for the most up-to-date specifications of PRODUCT(S). Not all PRODUCT(S) and/or types are available in every country. Please check with an NEC sales representative for availability and additional information.

No part of this customer notification may be copied or reproduced in any form or by any means without prior written consent of NEC. NEC assumes no responsibility for any errors that may appear in this customer notification. NEC does not assume any liability for infringement of patents, copyrights or other intellectual property rights of third parties by or arising from the use of PRODUCT(S) listed in this customer notification or any other liability arising from the use of such PRODUCT(S).

No license, express, implied or otherwise, is granted under any patents, copyrights or other intellectual property rights of NEC or others. Descriptions of circuits, software and other related information in this customer notification are provided for illustrative purposes of PRODUCT(S) operation and/or application examples only. The incorporation of these circuits, software and information in the design of customer's equipment shall be done under the full responsibility of customer. NEC assumes no responsibility for any losses incurred by customers or third parties arising from the use of these circuits, software and information.

While wherever feasible, NEC endeavors to enhance the quality, reliability and safe operation of PRODUCT(S) the customer agrees and acknowledges that the possibility of defects and/or erroneous thereof cannot be eliminated entirely. To minimize risks of damage to property or injury (including death) to persons arising from defects and/or errors in PRODUCT(S) the customer must incorporate sufficient safety measures in their design, such as redundancy, fire-containment and anti-failure features.

The customer agrees to indemnify NEC against and hold NEC harmless from any and all consequences of any and all claims, suits, actions or demands asserted against NEC made by a third party for damages caused by one or more of the items listed in the enclosed table of content of this customer notification for PRODUCT(S) supplied after the date of publication.

PRODUCT(S) are classified into the following three quality grades: "Standard", "Special" and "Specific". The "Specific" quality grade applies only to PRODUCT(S) developed based on a customer-designated "quality assurance program" for a specific application. The recommended applications of PRODUCT(S) depend on its quality grade, as indicated below. Customers must check the quality grade of each PRODUCT(S) before using it in a particular application.

- "Standard": Computers, office equipment, communications equipment, test and measurement equipment, audio and visual equipment, home electronic appliances, machine tools, personal electronic equipment and industrial robots
- "Special": Transportation equipment (automobiles, trains, ships, etc.), traffic control systems, anti-disaster systems, anti-crime systems, safety equipment and medical equipment (not specifically designed for life support).
- "Specific": Aircraft, aerospace equipment, submersible repeaters, nuclear reactor control systems, life support systems and medical equipment for life support etc.

The quality grade of PRODUCT(S) is "Standard" unless otherwise expressly specified in NEC data sheets or data books, etc. If customers wish to use PRODUCT(S) in applications not intended by NEC, they must contact NEC sales representative in advance to determine NEC's willingness to support a given application.

If the supplied goods/information are subject to Japanese, German, European and/or North American export controls, the customer shall comply with the relevant export control regulations in the event that the goods are exported and/or re-exported. If deliveries are exported without payment of duty at the request of the customer, the customer accepts liability for any subsequent customs administration claims with respect to NEC.

- Notes:**
- (1) "**NEC**" as used in this statement means NEC Electronics Corporation and also includes its direct or indirect owned or controlled subsidiaries.
 - (2) "**PRODUCT(S)**" means any product developed or manufactured by or for NEC (as defined above).

Table of Contents

Table of Contents	3
(A) Table of Operating Precautions for the IDE EW78K.....	4
(B) Table of Operating Precautions for the Assembler A78K	4
(C) Table of Operating Precautions for C/C++ Compiler ICC78K.....	5
(D) Table of Operating Precautions for the Linker XLINK	7
(E) Table of Operating Precautions for C-SPY Debugger CS78K.....	8
(F) Table of Operating Precautions for the Assembler A78K0R.....	10
(G) Table of Operating Precautions for C/C++ Compiler ICC78K0R.....	11
(H) Description of Operating Precautions for the IDE EW78K	12
(I) Description of Operating Precautions for the Assembler A78K.....	23
(J) Description of Operating Precautions for the C/C++ Compiler ICC78K.....	25
(K) Description of Operating Precautions for Linker (XLINK)	43
(L) Description of Operating Precautions for Debugger (C-SPY).....	49
(M) Description of Operating Precautions for the Assembler A78K0R	64
(N) Description of Operating Precautions for the C/C++ Compiler ICC78K0R.....	70
(O) Valid Specification	85
(P) Revision History.....	85

(A) Table of Operating Precautions for the IDE EW78K

No.	Outline	Version	EW78K					
			4.3a	4.4b	4.6b	4.8a	5.2d	5.5.0
A2	An empty Workspace can not be saved		x	x	x	x	x	x
A4	Supported Path Length is limited		x	✓	✓	✓	✓	✓
A5	Source Files can not be added directly to a user defined Group		x	✓	✓	✓	✓	✓
A6	Project Files using output file paths containing illegal drive letters can not be opened		x	x	x	✓	✓	✓
A7	Wrong Definition of RAM segments in XCL-file templates for 78K0S/Kx1+ devices		✓	✓	x	✓	✓	✓
A8	Code Banking Information must be modified by the User		-	-	x	✓	✓	✓
A9	Corrupt Default-Values for Near constant location Definition		-	-	✓	✓	✓	✓
A10	Usage of Soft-Links in output path definition could cause the IDE to link two copies of the output files in the Workspace Windows		x	x	x	x	x	✓
A11	78K0R: Project settings for near-constant-location are not saved.		✓	✓	x	x	x	✓
A12	Heap size input value is limited to 64KB		x	x	x	x	x	✓
A13	Linker output file in format IEEE695 is not be generated		✓	✓	x	x	x	✓
A14	Empty Go to Function Window		-	-	x	x	x	x
A15	Corrupted Default-File Filter		✓	✓	✓	✓	x	✓

- x: Applicable
- ✓: Not applicable
- : Not checked

(B) Table of Operating Precautions for the Assembler A78K

No.	Outline	Version	A78K					
			4.30a	4.40a	4.50a	4.60a	4.61a	4.62a
B1	RSEG Directives can not be used in Macro Definitions		x	x	x	x	x	x
B3	It is not possible to use an assembler DEFINE to an external symbol		x	x	✓	✓	✓	✓
B5	EVEN Directive doesn't align Data to even Address.		x	x	✓	✓	✓	✓

- x: Applicable
- ✓: Not applicable
- : Not checked

(C) Table of Operating Precautions for C/C++ Compiler ICC78K

No.	Outline	ICC78K						
		Version	4.50b	4.50c	V4.50e	4.60a	V4.61a	V4.62a
C5	No compiler message in case of a variable redefinition of the same datatype but with the different object attribute		x	x	x	x	x	x
C29	No message about MISRA Rule 1 violation		x	x	x	✓	✓	✓
C37	Warning [Pe177] generated by fault		x	x	x	✓	✓	✓
C38	Fatal error in case of using experimental option <code>-mfc</code>		x	x	x	✓	✓	✓
C39	Fatal error in case of using C++-style definition of a local variable		x	x	x	✓	✓	✓
C42	Internal compiler error for bit-test of array element (78K0S core only)		✓	✓	✓	✓	✓	✓
C43	Internal compiler error in case of using a default segment name for a user-defined segment		✓	✓	✓	✓	✓	✓
C44	Register-bank selection of interrupt function may be ignored		x	✓	✓	✓	✓	✓
C45	Internal Compiler Error may occur if calculation result is zero		x	x	x	✓	✓	✓
C46	Internal Compiler Error may occur if instruction <code>DBNZ</code> is used		✓	x	x	✓	✓	✓
C47	Internal Compiler Error occurs if bit complement and bit-and operation are combined in one command		x	✓	✓	✓	✓	✓
C48	Wrong code generated for access to multi-dimensional array		x	x	x	✓	✓	✓
C49	Compilation process can not be completed		✓	x	x	✓	✓	✓
C50	Spurious linker warning about conflicting data types		x	x	x	✓	✓	✓
C51	Extended EC++: Instantiating a template class may cause an internal error		x	x	x	✓	✓	✓
C52	Wrong code may be generated if the intrinsic function <code>'__get_interrupt_state'</code> is used		x	x	x	✓	✓	✓
C53	Internal Compiler Error occurs if second instruction parameter is a SFR-address		✓	x	x	✓	✓	✓
C54	Fatal Error (Uncontrolled termination) occurs if option <code>-Ohs</code> is used		✓	✓	✓	x	✓	✓
C55	MISRA C 2004 Rule 17.4 triggered by mistake		✓	✓	✓	x	✓	✓
C56	Banked Memory Model: Stack corrupted by wrongly generated code		x	x	x	x	✓	✓
C57	Banked Memory Model: Function Parameter not set		✓	✓	✓	x	✓	✓
C58	Wrong parameter passing to library function for signed 32bit comparison		✓	✓	✓	x	✓	✓
C59	Internal Compiler error in functions using an endless loop		x	x	x	x	✓	✓
C60	Wrong code generated for masking a bit of 16bit-high byte		✓	x	x	✓	✓	✓

Operating Precautions for EW78K-xxxx-EE

No.	Outline	Version	ICC78K					
			4.50b	4.50c	V4.50e	4.60a	V4.61a	V4.62a
C61	Missing Warning about change of sign due to integer conversion		x	x	x	x	x	✓
C62	Usage of uninitialized carry-flag		x	x	✓	✓	✓	✓

- x: Applicable
- ✓: Not applicable
- : Not checked

(D) Table of Operating Precautions for the Linker XLINK

No.	Outline	XLINK									
		Version	4.60a	4.60c	4.60f	4.60g	4.60i	4.61c	4.61h	4.61l	4.61n
D3	Breakpoint cannot be defined in Function (only XCOFF78K Format)	x	x	x	x	x	x	x	x	x	x
D12	Memory Bank Area is not filled up	x	✓	✓	✓	✓	✓	✓	✓	✓	✓
D13	Corrupted IRQ table for 78K0R devices in case of using the XCOFF78K output format	x	✓	✓	✓	✓	✓	✓	✓	✓	✓
D14	Due to a wrong symbol definition XLINK error message [e149] is generated	Please have a look at item C36 or G4									
D15	Unused odd address isn't filled up	x	✓	✓	✓	✓	✓	✓	✓	✓	✓
D16	Range Error occurred by mistake	x	x	✓	✓	✓	✓	✓	✓	✓	✓
D17	Error in 78K0R xcl-file (Ink78f11xx_xx.xcl) templates	x	x	✓	✓	✓	✓	✓	✓	✓	✓
D18	Missing information for far pointer in XCOFF78K output format	x	x	x	x	✓	✓	✓	✓	✓	✓
D19	Spurious linker warning about type conflict	Please have a look at item C50 or G19									
D21	Output file format UBROFF5: Error [e62] is generated erroneously if multiple modules are defined in one assembler source file	✓	✓	✓	✓	✓	x	✓	✓	✓	✓
D22	Output file format IEEE695: Missing enum datatype debug information	x	x	x	x	x	x	x	✓	✓	✓
D23	Output file format XCOFF78K: Usage of untyped segments may cause a corrupted file	✓	✓	✓	✓	✓	x	x	✓	✓	✓
D24	Output file format RAW-BINARY: XLINK may hang up	✓	✓	✓	✓	✓	✓	x	✓	✓	✓

- x: Applicable
- ✓: Not applicable
- : Not checked

(E) Table of Operating Precautions for C-SPY Debugger CS78K

No.	Outline	CS78K								
		Version	4.40a	4.40b	4.40c	4.50a	4.50b	4.60a	4.60b	4.62a
E24	C-SPY Driver for 'IECUBE': Real-time Memory Window Update interrupts application		x	✓	✓	✓	✓	✓	✓	✓
E25	Starting C-SPY by command line: Wrong Simulator started		x	x	x	x	x	✓	✓	✓
E26	Starting C-SPY by command line: C-SPY driver for 'IECUBE' crashes in case of using 78K0R emulator		x	x	x	x	x	✓	✓	✓
E27	Event-Breakpoint is deleted incompletely		x	x	x	x	x	✓	✓	✓
E28	C-SPY Driver for 'MINICUBE': Wrong display of main clock source of QB-78K0MINI-EE		x	x	x	✓	✓	✓	✓	✓
E29	C-SPY Driver for 'IE-78K': C-SPY fatal error in case of illegal SFR access		x	x	x	✓	✓	✓	✓	✓
E30	C-SPY Driver for 78K0R 'IECUBE' or 'MINICUBE': Fatal error after selecting 'SFR' in disassembly window		x	x	x	x	x	✓	✓	✓
E31	C-SPY Driver for 78K0R 'IECUBE' or 'MINICUBE': Memory read access by macro is blocked		x	x	✓	✓	✓	✓	✓	✓
E32	Code Coverage information is incomplete in case of using banked memory systems		x	x	✓	✓	✓	✓	✓	✓
E33	C-SPY Driver for 78K0R 'MINICUBE': The input field for the main clock source allows only selecting a value from a predefined list.		x	x	x	✓	✓	✓	✓	✓
E34	If the same name is used for a data-object and for a data-type, this data-object can not be displayed in the Watch Window		x	x	x	x	x	✓	✓	✓
E35	Argument variables can not be used to define a code breakpoint by source location		x	x	x	x	x	✓	✓	✓
E36	C-SPY Driver for 78K0R Simulator: Instruction 'mov memory_location[C],A' simulated incorrectly		x	x	x	✓	✓	✓	✓	✓
E37	C-SPY Driver for 78K0R IECUBE: OP-Fetch before execution can not be defined		x	x	x	x	x	✓	✓	✓
E38	C-SPY Driver or TK78K: Download to memory banks failed		x	x	x	x	✓	✓	✓	✓
E39	C-SPY Driver for 78K0R: High Byte of Program Counter (bit16-bit23) is set to 0x00		x	x	x	x	x	✓	✓	✓

Operating Precautions for EW78K-xxxx-EE

No.	Outline	Version	CS78K							
			4.40a	4.40b	4.40c	4.50a	4.50b	4.60a	4.60b	4.62a
E40	C-SPY Driver for 78K0R: A file in Intel-Hex- or Motorola-S-Record format can not be downloaded		x	x	x	x	x	✓	✓	✓
E41	C-SPY Simulator Driver: Wrong mask-flag is used to control an interrupt		x	x	x	x	x	✓	✓	✓
E42	C-SPY 78K0 IECUBE Driver: Full trace break doesn't work		x	x	x	x	x	✓	✓	✓
E43	C-SPY 78K0R Simulator Driver: Interrupt simulation only works correct at priority level three.		x	x	x	x	x	x	x	✓
E44	C-SPY 78K0 MINICUBE2 Driver: Error message about old firmware version		✓	✓	✓	✓	✓	✓	x	✓
E45	C-SPY all Drivers: Update Time Watch Window		✓	✓	✓	✓	✓	x	x	✓
E46	C-SPY Simulator Driver: Incorrect Value shown in Live-Watch Window		x	x	x	x	x	x	x	✓
E47	C-SPY 78K0 MINICUBE Driver: Incorrect System Clock Selection		x	x	x	x	x	x	x	✓
E48	Incorrect Variable Address may be displayed in Event Window or Watch Window		x	x	x	x	x	x	x	✓
E49	Stack Initialization in default cstartup-module triggers C-Spy Debugger stack observation		✓	✓	✓	✓	✓	x	x	✓
E50	Wrong display of array in C-Spy Watch Window		x	x	x	x	x	x	x	✓
E51	C-SPY 78K Simulator Driver: Wrong macro access to 16bit data		x	x	x	x	x	x	x	✓
E52	C-SPY 78K: Displayed floating point value in watch window may be wrong		✓	✓	✓	✓	✓	x	x	✓

x: Applicable

✓: Not applicable

- : Not checked

(F) Table of Operating Precautions for the Assembler A78K0R

No.	Outline	Version	A78K0R					
			4.40a	4.50a	4.60a	4.61a	4.62a	
F1	RSEG Directives can not be used in Macro Definitions		x	x	x	x	x	
F2	It is not possible to use an assembler DEFINE to an external symbol		x	✓	✓	✓	✓	
F4	EVEN Directive doesn't align Data to even Address.		x	✓	✓	✓	✓	
F5	Automatic Replacement of DBNZ Instruction causes Linker Error Message		x	✓	✓	✓	✓	
F6	Invalid Register in XCH Instruction causes the generation of wrong Op-Code		x	✓	✓	✓	✓	
F7	Invalid XCH instruction doesn't cause a syntax error		x	x	✓	✓	✓	
F8	Wrong Op-Code generated for MOV <register>, SFR-address instruction		x	x	✓	✓	✓	
F9	Illegal MOV instruction is accepted and wrong Op-Code is generated.		x	x	x	✓	✓	
F10	Invalid operand of branch instruction causes fatal assembler error		x	x	x	✓	✓	
F11	Illegal indirect MOVW instruction is accepted and wrong Op-Code is generated		x	x	x	x	✓	
F12	Illegal Op-Code generated if SFR symbol is defined after the usage		x	x	x	x	✓	

- x: Applicable
- ✓: Not applicable
- : Not checked

(G) Table of Operating Precautions for C/C++ Compiler ICC78K0R

No.	Outline	ICC78K0R						
		Version	4.50a	4.50b	4.50c	4.60a	V4.61a	V4.62a
G6	Warning [Pe177] generated by fault		x	x	x	✓	✓	✓
G7	Fatal error in case of using experimental option -mfc		x	x	x	✓	✓	✓
G11	Internal compiler error occurs if a default segment name is used for a user-defined segment		x	✓	✓	✓	✓	✓
G12	Wrong access to far and byte-aligned structure		x	✓	✓	✓	✓	✓
G13	Wrong code generated for indirect memory access		x	x	✓	✓	✓	✓
G14	Register-bank selection of interrupt function may be ignored		x	x	✓	✓	✓	✓
G15	Wrong access to local variable located on stack		x	x	✓	✓	✓	✓
G16	Internal Compiler Error may occur if calculation result is zero		x	x	x	✓	✓	✓
G17	Internal Compiler Error occurs if bit complement and bit-and operation are combined in one command		x	x	x	✓	✓	✓
G18	Wrong code generated for access to multi-dimensional array		x	x	x	✓	✓	✓
G19	Spurious linker warning about conflicting data types		x	x	x	✓	✓	✓
G20	Extended EC++: Instantiating a template class may cause an internal error		x	x	x	✓	✓	✓
G21	Internal Compiler Error occurs if numeric constant is used as function pointer		x	x	x	✓	✓	✓
G22	Fatal Error (Uncontrolled termination) occurs if option -Ohs is used		✓	✓	✓	x	✓	✓
G23	MISRA C 2004 Rule 17.4 triggered by mistake		✓	✓	✓	x	✓	✓
G24	DLIB Floating Point Function overwrites SADDR area		x	x	x	x	✓	✓
G25	Misaligned structure access		✓	✓	✓	✓	x	✓
G26	Wrong parameter passing of far pointer		x	x	x	x	x	✓
G27	Missing Warning about change of sign due to integer conversion		x	x	x	x	x	✓
G28	Delayed insertion of DI instruction		x	x	x	x	x	✓
G29	Misaligned 16bit-access		x	x	x	x	x	✓

x: Applicable

✓: Not applicable

- : Not checked

(H) Description of Operating Precautions for the IDE EW78K

No. A2	An empty workspace can not be saved
	<p><u>Details</u></p> <p>Although it is described in the user's manual an empty workspace can not be saved.</p> <p><u>Workaround</u></p> <p>Add at least one project to the workspace before saving. The project may be an empty project.</p>
No. A4	Supported Path Length is limited
	<p><u>Details</u></p> <p>The supported path length to project files by the Embedded Workbench is limited to about 100 characters. If this limit is exceeded the project file cannot be opened anymore and you received the following error message:</p> <p>Cannot find the file 'C:\...\<projectname.ewp>' (or one of its components). Make sure the path and filename are correct and that all required libraries are available.</p> <p><u>Workaround</u></p> <p>Reduce the path length.</p>
No. A5	Source Files can not be added directly to a user defined Group
	<p><u>Details</u></p> <p>Source files can not be added directly to a user defined group, because the in the 'Add Files...' dialogue there is no field to specify a group.</p> <p><u>Workaround</u></p> <p>Select the group in the Workspace-Window before open the 'Add Files...' dialogue. The files will be added automatically to the selected group.</p>

<p>No. A6</p>	<p>Project Files using output file paths containing illegal drive letters can not be opened</p>
	<p><u>Details</u></p> <p>Specifying absolute output directories with paths containing illegal drive letters caused IAR Embedded Workbench to exit without any further message.</p> <p><u>Workaround</u></p> <p>Before it is possible to open a project-file (*.ewp) using path with invalid drive letters, the project file has to be corrected manually with an editor of your choice:</p> <pre> <name>ExePath</name> <state>Debug\Exe</state> </option> <option> <name>ObjPath</name> <state>Debug\Obj</state> </option> <option> <name>ListPath</name> <state>Debug\List</state> </option> </pre>

<p>No. A7</p>	<p>Wrong Definition of RAM segments in XCL-file templates for 78K0S/Kx1+ devices</p>																
<p><u>Details</u></p> <p>In the XCL-file templates for the 78K0S/Kx1+ devices included in version V4.40a of the Embedded Workbench for 78K, the address-definition for the RAM segments is wrong. If you use this templates, the following a linker error will occur:</p> <pre>Fatal Error[e140]: The range declaration used in -Z(DATA)NEAR_I,NEAR_Z,NEAR_N,HEAP+_HEAP_SIZE=FE80-FE1F is illegal since 0xfe80 > 0xfelf. Fatal! Execution terminated...</pre> <p>The XCL-file templates for the following devices are effected:</p> <table border="0"> <thead> <tr> <th>Device</th> <th>XCL-file template</th> </tr> </thead> <tbody> <tr> <td>μPD78F9200</td> <td>lnk78f9200.xcl</td> </tr> <tr> <td>μPD78F9201</td> <td>lnk78f9201.xcl</td> </tr> <tr> <td>μPD78F9202</td> <td>lnk78f9202.xcl</td> </tr> <tr> <td>μPD78F9210</td> <td>lnk78f9210.xcl</td> </tr> <tr> <td>μPD78F9211</td> <td>lnk78f9211.xcl</td> </tr> <tr> <td>μPD78F9212</td> <td>lnk78f9212.xcl</td> </tr> <tr> <td>μPD78F9221</td> <td>lnk78f9221.xcl</td> </tr> </tbody> </table> <p><u>Workaround</u></p> <p>Please correct the above listed XCL-file templates as follows:</p> <pre>//----- - // Near data and heap segments. //----- -Z(DATA)NEAR_I,NEAR_Z,NEAR_N,HEAP+_HEAP_SIZE=FE80-FE1F //----- - // Stack segment. //----- -Z(DATA)CSTACK+_CSTACK_SIZE=FE80-FE1F</pre> <p>For the above listed devices the internal RAM area is smaller than the SADDR-area and therefore it is recommended to define all global variables as SADDR-variables to get short and fast code.</p>		Device	XCL-file template	μPD78F9200	lnk78f9200.xcl	μPD78F9201	lnk78f9201.xcl	μPD78F9202	lnk78f9202.xcl	μPD78F9210	lnk78f9210.xcl	μPD78F9211	lnk78f9211.xcl	μPD78F9212	lnk78f9212.xcl	μPD78F9221	lnk78f9221.xcl
Device	XCL-file template																
μPD78F9200	lnk78f9200.xcl																
μPD78F9201	lnk78f9201.xcl																
μPD78F9202	lnk78f9202.xcl																
μPD78F9210	lnk78f9210.xcl																
μPD78F9211	lnk78f9211.xcl																
μPD78F9212	lnk78f9212.xcl																
μPD78F9221	lnk78f9221.xcl																


No. A8

Code Banking Information must be modified by the User

Details


If the memory model 'Banked' or 'Standard allowing banking' is selected, the Code Banking information must be modified by the user according to the selected device, although a specific device is selected from the device list. The Embedded Workbench uses default values for the Code Banking definition independent of the selected device.

Example:



Workaround

Please enter the correct values according to the user's manual of the selected device:




No. A9

Corrupt Default-Values for Near constant location Definition


Details

If a specific 78K0R is selected the, default values for the Near constant location are corrupt.
Example:



Workaround

Please select the unspecified '78K0R' device:





Additionally the further device configuration must be done manually:
XCL-file selection in menu Project->Options->Linker->Config
DDF- file selection in menu Project->Options->Debugger

No. A10 Usage of Soft-Links in output path definition could cause the IDE to link two copies of the output files in the Workspace Windows

Details

If the IAR System soft-links (e.g. \$PROJ_DIR\$) are used to define the output file path, the Embedded Workbench may link two copies of the generated output file in the Workspace Window.

Example:



Workaround

Don't use soft-links in the output file path definition? The issue will be changed in next major update of EW78K.

No. A11	78K0R: Project settings for near-constant-location are not saved.
	<p><u>Details</u></p> <p>The size of the near-constant-location-area is not saved between two Embedded Workbench sessions. Instead, the default values are loaded.</p> <p><u>Workaround</u></p> <p>If the default setting is modified, please set the new values manually.</p>

No. A12	Heap size input value is limited to 64KB
	<p><u>Details</u></p> <p>The maximum heap size that can be entered in the Embedded Workbench GUI is 64KB. In case of entering a larger value the following error message is generated:</p> <div data-bbox="336 779 1099 1019" data-label="Image"> </div> <p><u>Workaround</u></p> <p>Please specify the heap-size directly in the used linker-control file instead of using the symbol '_HEAP_SIZE' defined in the Embedded Workbench GUI:</p> <pre>//----- // Heap segment //----- -Z(DATA)HEAP+0x12000=<start_address>-<end_address></pre> <p>The problem will be fixed in the next EW78K platform update.</p>

No. A13

Linker output file in format IEEE695 is not be generated



Details

If a 78K0R target device and the linker output file format IEEE695 is selected, no output file is selected and the following error message is generated:

Fatal Error[e92]: Cannot use the 'ieee695' output format with this cpu

Workaround

Please select another output file format (e.g. C-Spy Debug Format), enable the generation of a second output file, and select the format IEEE695 for the second output file:




The problem will be fixed in the next EW78K platform update.

No. A14


Empty Go to Function Window

Details

Depending on some source code constructions (e.g. using shift operator to initialize a structure element) the Go to Function Window may be empty.
 Correct Go to Function Window:



Empty Go to Function Window although there are several functions defined in the active source file:





Workaround

None. The problem will be fixed in the next EW78K platform update.

No. A15 Corrupted Default-File Filter

Details

The default file filter of the C-Spy file selection dialogue after pressing the button '...' of the code breakpoint 'Enter Location Window' is corrupted and therefore no files are listed although there are source files in the selected folder:



Workaround

Enter '*.*' as file name to get a list of all available source files and select the file.

(I) Description of Operating Precautions for the Assembler A78K

<p>No. B1</p>	<p>RSEG Directives can not be used in Macro Definitions</p>
	<p><u>Details</u></p> <p>The assembler calculates a wrong relative jump-distance if the RSEG directive is used within a macro definition:</p> <p><u>Example</u></p> <pre>mDummyMacro MACRO RSEG CODE NOP ENDM</pre> <p><u>Workaround</u></p> <p>Don't use the RSEG directive in macro definitions. The used code-segment must be defined in the code where the macro is expanded to.</p>
<p>No. B3</p>	<p>It is not possible to use an assembler DEFINE to an external symbol</p>
	<p><u>Details</u></p> <p>In case of using an assembler DEFINE to an external symbol, the linker will generate the following error:</p> <pre>Fatal Error[e20]: Corrupt file. External index out of range in module MODUL2 (C:\....\test.r26)</pre> <p><u>Example</u></p> <pre> EXTERN S2 SYM DEFINE S2</pre> <p><u>Workaround</u></p> <p>None. The assembler version V4.41a or later will generate an error for such cases.</p>

<p>No. B5</p>	<p>EVEN Directive doesn't align Data to even Address.</p>
<p><u>Details</u></p> <p>The EVEN directive aligns to an even address relative to the start module-startaddress of the segment instead of an absolute even address. In case of an odd module-startaddress also all symbols aligned with an even-directive are located at an odd address. In this case a linker error message will be generated for each access to the misaligned variable:</p> <pre>IAR Universal Linker V4.60A/386 Copyright 1987-2006 IAR Systems. All rights reserved.</pre> <p>Error[e18]: Range error, Even value expected File: H:\Data\...\even.asm, Line: 17 Source: MOVW S:integer1, AX Where \$ = test_even + 0x1 [0xA8] in module "even", offset 0x1 in segment part 1, segment CODE What: (integer2 + 2) & 1 [0x1] Allowed range: 0x0 - 0x0 Operand: integer2 [0xfe23] in module even, Offset 0x2 in segment part 0, segment SADDR_Z</p> <p><u>Example</u></p> <pre>RSEG SADDR_Z CharVar1: DS 1 ALIGNRAM 1 IntVar1: DS 2</pre> <p><u>Workaround</u></p> <p>Please align the segment-start address to an even address:</p> <pre>RSEG SADDR_Z(1) CharVar1: DS 1 ALIGNRAM 1 IntVar1: DS 2</pre>	

(J) Description of Operating Precautions for the C/C++ Compiler ICC78K

No. C5	No compiler message in case of a variable redefinition of the same data type but with the different object attribute
	<p><u>Details</u></p> <p>The compiler doesn't generate a message for the user if a variable is redefined with the same data type but with a different object attribute.</p> <p>Example:</p> <pre>unsigned int i; __no_init unsigned int i;</pre> <p><u>Workaround</u></p> <p>Manual check by the user required.</p>

No. C29	No message about MISRA Rule 1 violation
	<p><u>Details</u></p> <p>MISRA C rule 1 concerns the ISO 9899 C conformance without extension meaning strict ANSI C.</p> <p>When a project is compiled with IAR extensions and the first MISRA C rule enabled no errors or warnings come up to indicate this contradiction.</p> <p>Example:</p> <pre>volatile __saddr int i; __callt void test(void) { i++; }</pre> <p><u>Workaround:</u></p> <p>None.</p>

No. C37	Warning [Pe177] generated by fault
	<p><u>Details</u></p> <p>If a variable defined as ‘__root’ is additionally defined as ‘static’, the compiler will generate the warning message [Pe177] by fault:</p> <pre>Warning[Pe177]: variable "test1" was declared but never referenced</pre> <p>The keyword ‘__root’ informs the linker that the variable should be located even it is not referenced. This implies already that a variable might not be used in the module and that this declaration is done on purpose.</p> <p>Example:</p> <pre>static __root const char test1= 0x01;</pre> <p><u>Workaround:</u></p> <p>The problem will be fixed in the next major update. So far please use one of the following workarounds:</p> <ol style="list-style-type: none"> 1) Don't define a variable as ‘__root’ and ‘static’ 2) Disable warning [Pe177] for such definitions: <pre>#pragma diag_suppress=Pe177 static __root const char test1 = 0x01; #pragma diag_default=Pe177</pre>
No. C38	Fatal error in case of using experimental option –mfc
	<p><u>Details</u></p> <p>If two static functions of the same name are exist in modules that are compiled simultaneously by using the currently experimental option –mfc, a fatal error occurs:</p> <pre>Internal Error: [CoreUtil/General]: OgModuleLables - label already defined. Fatal error detected, aborting.</pre> <p>Example:</p> <pre>source file f1.c: static unsigned char func1 (unsigned char p1) { // code doesn't matter return (1); } source file f1.c: static unsigned int func1 (unsigned int p1) { // code doesn't matter return (1); }</pre> <p><u>Workaround:</u></p> <p>The problem will be fixed in the platform release, when the option –mfc will be officially introduced (V4.4xx, schedule is December 2007)</p>

No. C39	Fatal error in case of using C++-style definition of a local variable
<p><u>Details</u></p> <p>If IAR Systems compiler extensions are enabled, it is allowed to define local variables directly before using them. But if such local variable is defined as static a fatal error is generated:</p> <p>Internal Error: [symbol_lookup_M31]: symbol not found for mode 1 (backend generating) (P0: 0, P1: 0)</p> <p>Example:</p> <pre>void test (void) { for(static int i = 0; i<10; i++); }</pre> <p><u>Workaround:</u></p> <p>Define local variables according to the ANSI C standard at the beginning of a function.</p> <pre>void workaround (void) { static int i; for(i = 0; i<10; i++); }</pre>	

No. C42	Internal compiler error for bit-test of array element (78K0S core only)
	<p><u>Details</u></p> <p>In case of using a 78K0S device (μPD78F9xxxx, μPD789xxxx) pointer or array expressions of objects located in the short address area that result in a bit test instruction cause the following internal error for 78K0S.</p> <p>Internal error [AsmLine - OgAsm]: Error [43] Illegal effective address Fatal error detected aborting</p> <p>Example:</p> <pre> unsigned char v1,v2; __saddr unsigned char buffer[5]; void test(void) { if(buffer[v1]&0x80) { v2=1; } } </pre> <p><u>Workaround:</u></p> <p>Locate the array in the standard RAM, i.e. remove the key word __saddr:</p> <pre> unsigned char v1,v2; unsigned char buffer[5]; void test(void) { if(buffer[v1]&0x80) { v2=1; } } </pre>

No. C43	Internal compiler error in case of using a default segment name for a user-defined segment.
	<p><u>Details</u></p> <p>In case of using a default segment name of the compiler for user-defined segment of constant data, an internal compiler error occurs after the warning about using a default segment name .</p> <p>Internal error [Front end]: Invalid C99 IL expression kind Fatal error detected aborting.</p> <p>Example:</p> <pre> #pragma location = "CODE" __root const unsigned char counter=23; void test(unsigned char *p1) { *p1=((volatile const unsigned char *)&counter); } </pre> <p><u>Workaround:</u></p> <p>Do not use the compiler default segment names for user-defined segments</p>

No. C44

Register-bank selection of interrupt function may be ignoredDetails

In case of using an optimization level higher than 'low' the compiler may ignore the register-bank selection of the user (#pragma bank) for some interrupt functions.

Example:

```
#include <io78f0893.h>
extern void f2 (unsigned char );

typedef enum {
    GPT_1,
    GPT_2
}ENUM1;
typedef enum {
    GPT_3,
    GPT_5
} ENUM2;
typedef struct {
    ENUM1      s1;
    unsigned char s2;
    void*      s3;
}STRUCT1_T;
typedef struct{
    ENUM2      s4;
    unsigned short s5;
} STRUCT2_T;

#pragma bank = 2
__interrupt void isr( void )
{
    unsigned short u16PR0sav, u16PR1sav;
    u16PR0sav = PR0 ;
    u16PR1sav = PR1 ;
    __enable_interrupt();

    if (ptr1[((unsigned char) 0)].s1 == GPT_1)    {
        array[((unsigned char) 0)].s4 = GPT_5;
    }
    f2( ((unsigned char) 0) );

    __disable_interrupt();
    PR0 = u16PR0sav;
    PR1 = u16PR1sav;
}

```

Workaround:

Please reduce the optimization level for the interrupt function, if the instruction 'SEL RB2' isn't generated for your interrupt function:

```
#pragma optimize = s 3
#pragma bank = 2
__interrupt void isr( void )
{
    ...
}

```

No. C45	Internal Compiler Error may occur if calculation result is zero
	<p><u>Details</u></p> <p>Code examples where a calculation result is zero may cause an internal compiler error.</p> <p>Example:</p> <pre>signed int i,k; int test(void) { k=90-(9-i)*10; }</pre> <p><u>Workaround:</u></p> <p>Try to rewrite the arithmetic expression to avoid a zero result:</p> <pre>int test (void) { k=90-(90-10*i); }</pre>

No. C46	Internal Compiler Error may occur if instruction DBNZ is used
	<p><u>Details</u></p> <p>If the instruction DBNZ is used an internal compiler error may occur:</p> <p>Internal Error: [CoreUtil/General]: Size mismatch for "DBNZ S:v1, ??test_0", inserted as 2 bytes, assembled as 3 bytes.</p> <p>Example:</p> <pre>__saddr unsigned char v1; void test (void) { if (!--v1){ ... } }</pre> <p><u>Workaround:</u></p> <p>Lower the optimization to level medium to avoid the usage of the instruction DBNZ</p> <pre>#pragma optimization = z 6 void test (void) { ... }</pre>

No. C47	Internal Compiler Error occurs if bit complement and bit-and operation are combined in one command
<p><u>Details</u></p> <p>If the C command to complement a special functions register bit is combined with a bit and command to mask a single bit and an assignment to an integer variable, an internal error occurs:</p> <p>Internal Error: [CoreUtil/General]: Illegal state</p> <p>Example:</p> <pre>#include <io78F0547_80.h> unsigned int IntVar; void test(void) { IntVar = ~P0_bit.no0 & 0x01; }</pre> <p><u>Workaround:</u></p> <p>Please split up the operations in separate lines of code.</p> <pre>unsigned int IntVar; void test(void) { IntVar = ~P0_bit.no0; IntVar = IntVar & 0x01; }</pre>	

No. C48	Wrong code generated for access to multi-dimensional array
<p><u>Details</u></p> <p>In a case of using optimization type speed level high, the compiler may generate wrong code for the access of multi-dimensional arrays.</p> <p>Example:</p> <pre>static void test (void) { unsigned short x, y; for (y = 0; y < 8; y++){ for (x = 0; x < 128; x++) { buffer[y][x] = 0x00; } } } void dummy(void) { test(); }</pre> <p><u>Workaround:</u></p> <p>Please reduce the optimization level to medium or use while instead of for loops.</p>	

No. C49	Compilation process can not be completed
	<p><u>Details</u></p> <p>In a case of using optimization level high and allow the usage of the worksegment, the compilation process can not be completed for certain code examples. No error message is generated; the compilation process must be terminated manually.</p> <p><u>Workaround:</u></p> <p>Please reduce the optimization level to medium or don't allow worksegment usage.</p>
No. C50	Spurious linker warning about type conflict
	<p><u>Details</u></p> <p>The compiler could in some cases (e.g. high level of nested typedef types) emit data type incorrect debug information for typedef types. When linking with XLINK, this could result in a spurious type conflict warning:</p> <p>Warning[w6]: Type conflict for external/entry "<object-name>", in module file2 against external/entry in module file1; different types</p> <p>The generated code is correct.</p> <p><u>Workaround:</u></p> <p>Please reduce the level of nested typedef types.</p>
No. C51	Extended EC++: Instantiating a template class may cause an internal error
	<p><u>Details</u></p> <p>Instantiating a template class like vector on a function type may result in an internal error</p> <p>Internal Error: [Visit types]: Error type</p> <p>Example:</p> <pre>enum eState { state1, state2}; template <class T, T init> class CEnum { public: CEnum() {m_Value = init; } operator unsigned char () const {return (unsigned char)m_Value; } void operator +=(unsigned char arg) {m_Value = (T)(m_Value + arg) } private: T m_Value; }; static __saddr __no_init CEnum<enum eState, state1> state; void test(void) { state += state2; }</pre> <p><u>Workaround:</u></p> <p>None.</p>

No. C52	Wrong code may be generated if the intrinsic function ‘__get_interrupt_state’ is used
	<p><u>Details</u></p> <p>If the intrinsic functions ‘__get_interrupt_state’ and ‘__disable_interrupt’ are used in the same function, the compiler may store the program status word (PSW) to a register before interrupts are disabled instead when the function ‘__get_interrupt_state’ is called. The register content instead of the actual PSW content is used for further actions.</p> <p>Example:</p> <pre>#include <intrinsics.h> void test(void) { __disable_interrupt(); { istate_t is = __get_interrupt_state(); __enable_interrupt(); __set_interrupt_state(is); } }</pre> <p><u>Workaround:</u></p> <p>No direct workaround, but an assembler function can be used as replacement</p>

No. C53	Internal Compiler Error occurs if second instruction parameter is a SFR-address
	<p><u>Details</u></p> <p>For the instructions ADD, ADDC, SUB, SUBC, AND, OR, XOR and CMP, when the first parameter is register A and the second parameter is an SFR address above the SADDR memory area, the SFR address is treated as a SADDR address. This causes an internal compiler error:</p> <p>Internal Error: [CoreUtil/General]: Size mismatch for "...", inserted as 2 bytes, assembled as 3 bytes.</p> <p>Example:</p> <pre>#include <io78f0515_48.h> unsigned char test(unsigned int p1) { unsigned char retVal = 0 ; while((0 == IF1H) && (0 != p1--)) { p1--; } return (retVal); }</pre> <p><u>Workaround:</u></p> <p>None. The problem will be fixed in V4.60a</p>

No. C54	Fatal Error (Uncontrolled termination) occurs if option <code>-Ohs</code> is used
	<p><u>Details</u></p> <p>If the following sample is compiled by using option <code>-Ohs</code> a fatal error occurs: Fatal Error[c0000005hìø_°a`_""°°_„ìø_^°°_"]: Uncontrolled termination In case of using WindowsXP the user is asked to inform Microsoft about this issue.</p> <p>Example:</p> <pre>typedef struct { unsigned char MyByte; }T_MYSTRUCT; extern void func1(unsigned char *, unsigned short , unsigned short); void func2(T_MYSTRUCT *p1, unsigned char p2) { unsigned short local; local = (0x0040) + (p2 * 10); func1((unsigned char*)p1,local,10); } unsigned char test(void) { unsigned char local1=201; unsigned char local2=0; T_MYSTRUCT local3; T_MYSTRUCT *plocal3 = &local3; do { func2(plocal3, local1); if (plocal3->MyByte != 0x00) { local2 ++; } local1++; } while (local1 < 204); return (local2); }</pre> <p><u>Workaround:</u></p> <p>Use either option <code>-Ohm</code> instead of option <code>-Ohs</code> or disable 'code inlining' by option <code>-no_inline</code> if option <code>-Ohs</code> is used</p>

No. C55	MISRA C 2004 Rule 17.4 triggered by mistake
	<p><u>Details</u></p> <p>MISRA C rule 17.4 is triggered by mistake for arrays included in structures: Error [Pm152]: array indexing shall only be applied to objects defined as an array type (MISRA C 2004 rule 17.4)</p> <p>Example:</p> <pre>typedef unsigned char uint8; void test(void); void test(void) { struct { uint8 u8Array[4]; } tStruct; tStruct.u8Array[0] = 5u; tStruct.u8Array[1] = tStruct.u8Array[0]; } </pre> <p><u>Workaround:</u></p> <p>Disable rule 17.4 by using the #pragma diag_suppress directive for source lines accessing an array included in a structure:</p> <pre>typedef unsigned char uint8; void test(void); void test(void) { struct { uint8 u8Array[4]; } tStruct; #pragma diag_suppress = Pm152 tStruct.u8Array[0] = 5u; tStruct.u8Array[1] = tStruct.u8Array[0]; #pragma diag_default = Pm152 } </pre>
No. C56	Banked Memory Model: Stack corrupted by wrongly generated code
	<p><u>Details</u></p> <p>If banked memory model and an optimization level larger than low is used, the compiler may generate wrong that corrupts the stack if a comparison of 32bit value with a constant is made. The example to demonstrate the occurrence is too complex to be listed in this document.</p> <p><u>Workaround:</u></p> <p>Reduce the optimization level for the function where the problem occurs by using the directive #pragma optimize=low.</p> <pre>#pragma optimization = low void fool (void) { ... } </pre>

No. C57**Banked Memory Model: Function Parameter not set**Details

If an optimization level larger than medium is used, the compiler generates wrong code by not passing the constant function parameter of the banked function 'func2' the following sample:

```
extern unsigned char global_1, buffer_1[8], buffer_2[8];
extern          void func1 (void);
extern          void func2 (unsigned char);
extern          void func3 (void);
extern __non_banked void func4 (unsigned char);

void test(void)
{
    if (buffer_1[1]=='Y') {
        if (buffer_1[2]=='S') {
            switch (buffer_1[3]) {
                case 0x11: {
                    func3();
                    buffer_1[2] = 'T';
                    break;
                }
                case 0x12:{
                    func2(1);
                    buffer_1[2] = 'T';
                    break;
                }
                default :
                {
                    buffer_2[2]='S';
                    func4(2);
                    break;
                }
            }
        }
        else {
            if (buffer_1[2]=='T') {
            }
            else {
                buffer_1[2]--;
            }
        }
    }
}
```

Workarounds:

1) Reduce the optimization level of the function where the problem occurs by using the directive #pragma optimize=medium.

```
#pragma optimization = low
void test (void)
{
    ...
}
```

2) Define function 'func2' as 'non-banked' function:

```
extern __non_banked void func2 (unsigned char);
```


No. C58	Wrong parameter passing to library function for signed 32bit comparison
	<p><u>Details</u></p> <p>If an optimization level low or higher is used, the compiler generates wrong code for the following sample. The parameter passing to the library function for the signed 32bit comparison is incorrect; the first parameter must be passed in register AX, BC.</p> <pre> #define HIBYTE(w) ((unsigned char)((w) >> 8) & 0x00FF) #define LOBYTE(w) ((unsigned char)(w) & 0x00FF) #define BUILD_WORD(h, l) (((unsigned short)(h) << 8) + (l)) unsigned short test(signed long i) { unsigned char local1, local2 = 0; i *= 10; if(i < 0){ local1 = 0x80; i = -i; } else { local1 = 0; } while(i > 0x7FF){ i /= 2; local2++; } if(local1) { i = ~(unsigned short)i + 1 & 0x7FF; } return BUILD_WORD(LOBYTE(i), HIBYTE(i) local2 << 3 local1); } </pre> <p><u>Workaround:</u></p> <p>1) Reduce the optimization level of the function where the problem occurs by using the directive #pragma optimize=none.</p> <pre> #pragma optimization = none unsigned short test(signed long i) { ... } </pre>

No. C59	Internal Compiler error in functions using an endless loop
	<p><u>Details</u></p> <p>Functions containing an if - statement using different amounts of stack and immediately followed by a 'while(1);' construction might generate an internal error.</p> <pre>#include <stdio.h> unsigned short s1, s2; extern unsigned short f1 (unsigned short, unsigned short); void main(void) { while (1) { if(s1 != s2) { printf("dummy text: 0x%hx vs 0x%hx \n",s1,s2); } while(1); } }</pre> <p><u>Workaround:</u></p> <p>Replace the endless loop while(1) by a loop using a variable:</p> <pre>#include <stdio.h> unsigned short s1, s2; extern unsigned short f1 (unsigned short, unsigned short); const unsigned char s3=0; void main(void) { while (1) { if(s1 != s2) { printf("dummy text: 0x%hx vs 0x%hx \n",s1,s2); } while(s3==0); } }</pre> <p>The problem will be fixed in the next compiler update.</p>

No. C60	Wrong code generated for masking a bit of 16bit-high byte
<p><u>Details</u></p> <p>In dependent of the used optimization level the compiler generates wrong code for comparing an unsigned 16bit value with a constant bit pattern with either one bit of the upper byte (high byte) set or cleared.</p> <pre>#define MASK 0x0200 typedef struct { unsigned short element1; } struct1; void test(struct1 * parameter1) { if ((parameter1->element1 & MASK) != 0) { ... } }</pre> <p><u>Workarounds:</u></p> <p>1) Casting the unsigned 16bit value to signed value:</p> <pre>void test(struct1 * parameter1) { if (((signed short)parameter1->element1) & MASK) != 0) { ... } }</pre> <p>2) Upgrade to a new compiler version V4.60a or later</p>	

No. C61	Missing Warning about change of sign due to integer conversion
<p>If the sign of a constant given in hexadecimal or octal format is changed due an integer conversion, the compiler doesn't generate a warning (Pe068).</p> <pre>short test (void) { return (0x8000); }</pre> <p><u>Workaround:</u></p> <p>Use the decimal format:</p> <pre>short workaround (void) { return (32768); }</pre> <p>Form the next compiler version onwards a remark will be generated if the sign of a constant given in hexadecimal or octal format is changed due to an integer conversion. As result the behavior will be the same for constants given in decimal and hexadecimal format.</p>	

No. C62	Usage of uninitialized carry-flag
	<p>If a speed-optimization level medium or higher is used, the compiler may use the carry flag before using initialize it. This problem is demonstrated in following sample in the following sample:</p> <pre> unsigned int v1; unsigned int v2; unsigned int v3; volatile unsigned int r1; void test(void) { unsigned char v4; signed int v5; static unsigned int v6; v4 = (v1/4 / 256)+1; v2 = (v1/4); /* error: CY isn't cleared before usage*/ v6 = (v1/4) ; v5 = v3 / 16 / v4; r1 = v6 + v2 + v5 + v4; } </pre> <p><u>Workaround:</u></p> <p>Reduce the optimization to low. In the special sample above a local temp variable can be used to avoid the problem:</p> <pre> void test(void) { unsigned char v4; signed int v5; static unsigned int v6; unsigned int temp = v1/4; v4 = (temp / 256)+1; v2 = temp; v6 = temp; v5 = v3 / 16 / v4; r1 = v6 + v2 + v5 + v4; } </pre> <p>To fix the problem, please download compiler patch V4.50e available at the IAR Systems MyPages area (www.iar.com -> Menu MyPages or http://supp.iar.com/MyPages/). Alternatively please feel free to contact the NEC software tool support team (software_support@eu.necel.com).</p>

(K) Description of Operating Precautions for Linker (XLINK)

<p>No. D3</p>	<p>Breakpoint cannot be defined in function (only XCOFF78K Format)</p>
	<p><u>Details</u></p> <p>In case of using a function with a name of 32 characters (or more) and using static local variables a debug problem occurs in the XCOFF78K format if the format modifier <code>-y</code> is set to truncate long symbol names. It is not possible to define a breakpoint within the function.</p> <p><u>Workaround</u></p> <p>Don't use the format modifier <code>-y</code> for the XCOFF78K format. The format modifier <code>-y</code> was required by previous versions of the NEC debuggers. The format modifier is not necessary anymore if the following debugger versions are used: ID78K0x-NS: V2.50 or later ID78K0x-QB: V2.80 or later</p>

No. D12 Memory Bank Area is not filled up.

Details

Although the options -H and -h are used correctly, an area at the end of a memory bank may not be filled up. This is documented in the linker map-file:

```

*****
*
*          CHECKSUMS
*
*****

Symbol      Checksum  Memory  Start      End      Initial value
-----
__checksum  0x7f2f   CODE    0000 - 7FFD      0x0
            8000 - BFFC
            CODE 00018000 - 0001BFFD
            CODE 00028000 - 0002BFFF
            CODE 00038000 - 0003BFFF
    
```

The correct CKECHSUMS section should be as follows:

```

*****
*
*          CHECKSUMS
*
*****

Symbol      Checksum  Memory  Start      End      Initial value
-----
__checksum  0x7f2f   CODE    0000 - 7FFD      0x0
            8000 - BFFF
            CODE 00018000 - 0001BFFF
            CODE 00028000 - 0002BFFF
            CODE 00038000 - 0003BFFF
    
```

Workarounds

Either use the previous linker to version V4.59q until V4.60b or later is available or fill-up the areas manually by adding the following lines of source code:

```

__root const unsigned char fill1[3] @ 0x0BFFD = {0xFF,0xFF,0xFF};
__root const unsigned char fill2[2] @ 0x1BFFE = {0xFF,0xFF};
    
```


No. D13	Corrupted IRQ table for 78K0R devices in case of using the XCOFF78K output format
	<p><u>Details</u></p> <p>In case of using the XCOFF78K format and a device of the 78K0R-series, the IRQ table contains wrong entries. The addresses of the ISRs are fixed to 0x0000.</p> <p><u>Workarounds</u></p> <p>Upgrade the linker to version V4.60c or later.</p>
No. D15	Unused odd address isn't filled up
	<p><u>Details</u></p> <p>In some cases an unused odd address directly after a constant located by absolute memory allocation is not filled-up, although the options -H and -h are used.</p> <p>Example:</p> <pre>__root const unsigned char const1 @ 0x1080 = 0x01;</pre> <p>The following address 0x01081 is not filled up, although -h00000-BFFF is used</p> <p><u>Workarounds</u></p> <p>Upgrade the linker to version V4.60c or later.</p>
No. D16	Range Error occurred by mistake
	<p><u>Details</u></p> <p>In some cases the definition of a near constant causes a range error by mistake.</p> <pre>Error[e18]: Range error, Limit exceeded</pre> <pre>Where \$ = main + 0x1 [0x8C6] in module "main" (.main_z3.r26), offset 0x1 in segment part 4, segment CODE What: (array + 1) [0x1001] Allowed range: 0xF0000 - 0xFFFFF Operand: array [0x1001] in module main (.main_z3.r26), Offset 0x1 in segment part 3, segment NEAR_CONST</pre> <p>Example:</p> <pre>const __near unsigned char array[10]={0,1,2,3,4,5,6,7,8,9};</pre> <p><u>Workarounds</u></p> <p>Use the option -Rw to reduce the message level to warning. Now an output file is generated and it is still possible to be noticed about other range problems. The problem will be fixed in the next major update V4.50a.</p>

No. D17	Error in 78K0R xcl-file (lnk78f11xx_xx.xcl) templates
	<p><u>Details</u></p> <p>If a module includes object definitions of a size of more than 64KB, error will occur:</p> <p>Error[e16]: Segment XCODE (size: 0x16905 align: 0) is too long for segment definition. At least 0x6905 more bytes needed. The problem occurred while processing the segment placement command "-Z(CODE)XCODE=[000D8-3FFFF]/10000", where at the moment of placement the available memory ranges were "CODE:ef3-ceff, CODE:cf2a-ffff, CODE:10000-1ffff, CODE:20000-2ffff, CODE:30000-3ffff"</p> <p>The problem is caused by an incorrect definition of the far code segment XCODE in the 78K0R xcl-file templates.</p> <pre>//----- // Far functions code segment. //----- -Z(CODE)XCODE=[000D8-3FFFF]/10000</pre> <p><u>Workarounds</u></p> <p>Please correct the definition by using the option -P (=packed segments):</p> <pre>//----- // Far functions code segment. //----- -P(CODE)XCODE=[000D8-3FFFF]/10000</pre> <p>Corrected XCL-file templates will be included in the EW78K V4.50a and later.</p>

No. D18	Missing information for far pointer in XCOFF78K output format
	<p><u>Details</u></p> <p>Some information for far pointer is missing in the debug format XCOFF78K and therefore the highest byte (bit16 –bit23) of the pointer address is displayed incorrect in the watch window of the NEC debugger ID78K0R-QB. The generated code is correct.</p> <p>Example:</p> <pre>__root const unsigned char test[5] = {0,1,2,3,4}; void test (void) { const unsigned char __far *LocalFarPointer; LocalFarPointer = &test[0]; ... }</pre> <p><u>Workarounds</u></p> <p>The problem will be fixed in XLINK V4.60i and later.</p>

No. D21	Output file format UBROFF5: Error [e62] is generated erroneously if multiple modules are defined in one assembler source file
	<p><u>Details</u></p> <p>The linker error message [e62] is generated erroneously if multiple modules are defined in one assembler source file and the output file format UBROFF5 is selected:</p> <p>Error[e62]: File name "C:\...\test.s26" used for multiple files</p> <p>Example:</p> <pre> MODULE m1 ; some assembler code ENDMOD MODULE m1 ; some assembler code ENDMOD END </pre> <p>Linker output format selection: -FUBROFF5</p> <p><u>Workarounds</u></p> <p>Define only one module per assembler source file or use the current version of the UBROFF format. The problem will be fixed in a future linker version.</p>

No. D22	Output file format IEEE695: Missing enum datatype debug information
	<p><u>Details</u></p> <p>An IEEE695-format output doesn't include debug information of enum-datatypes.</p> <p>Example:</p> <pre> enum colour {rot, blau, gruen, gelb, braun}; enum colour my_enum; void test (void) { if (my_enum <= braun) { my_enum++; } } </pre> <p>Linker output format selection: -FIEEE695</p> <p><u>Workarounds</u></p> <p>None. The problem will be fixed in a future linker version.</p>

No. D23	Output file format XCOFF78K: Usage of untyped segments may cause a corrupted file
<p><u>Details</u></p> <p>If untyped segments (e.g RSEG MYDATA(1)) are used in an assembler file, the generated NEC debug file (format xcoff78) may be corrupted. The NEC debugger will generate the following error message if such file shall be downloaded:</p> <div data-bbox="708 456 1104 692" style="text-align: center;">  </div> <p><u>Workarounds</u></p> <p>Please use only typed segment:</p> <p>RSEG MYDATA(1):DATA</p>	

No. D24	Output file format RAW-BINARY: XLINK may hang up
<p><u>Details</u></p> <p>If an output file in RAW-BINARY format shall be generated the linker may hang and the process must be manually killed.</p> <p><u>Workarounds</u></p> <p>None. The problem will be fixed in a future version</p>	

(L) Description of Operating Precautions for Debugger (C-SPY)

No. E24	C-SPY Driver for 'IECUBE': Realtime Memory Window Update interrupts application
	<p><u>Details</u></p> <p>To update the content of the Realtime Memory Window a running application is interrupted by the C-SPY debugger. This procedure is started when the Realtime Memory is Window is opened once and is continued even if the Real-time Memory is closed again.</p> <p><u>Workaround</u></p> <p>The issue will be fixed in version V4.40b or later. To disable the procedure in version V4.30x and V4.40a use the following procedure:</p> <ul style="list-style-type: none"> - close the Real-time Memory Window - close the Embedded Workbench - delete the subfolder 'settings' of the project folder <p>In the next debug-session the application isn't interrupted anymore until the Real-time Memory Window isn't opened.</p>
No. E25	Starting C-SPY by command line: Wrong Simulator started
	<p><u>Details</u></p> <p>In case of calling C-SPY from the command line, independent of the option setting in command line or the project options always the simulator for 78K0 is started.</p> <p><u>Workaround</u></p> <p>Please use a 'Debug-project' to start a debug session for an externally build application. The issue will be fixed in future update (V4.50a or later).</p>
No. E26	Starting C-SPY by command line: C-SPY driver for 'IECUBE' crashes in case of using 78K0R emulator
	<p><u>Details</u></p> <p>In case of calling C-SPY from the command line with the driver for IECUBE and a 78K0R emulator, the debugger crashes. This is independent from the debug project.</p> <p><u>Workaround</u></p> <p>Please use a 'Debug-project' to start a debug session for an externally build application. The issue will be fixed in a future update (V4.50a or later).</p>

No. E27	Event-Breakpoint is deleted incompletely
	<p><u>Details</u></p> <p>If an event-breakpoint is deleted in the Breakpoint Window while the Event Window is open, the breakpoint is only removed from the Breakpoint Window, but not deleted.</p> <p>Although the breakpoint isn't listed anymore in the Breakpoint Window, it is still active. The corresponding event can not be deleted, because it is still in use.</p> <p><u>Workaround</u></p> <p>Please close the Event Window before deleting a breakpoint in the Breakpoint Window. If an event-breakpoint had been deleted while the Event Window was open, the breakpoint can not be deleted anymore by the C-SPY debugger. To remove the breakpoint please close the Embedded Workbench and delete the file '<code><project_name>.dni</code>' in the subfolder 'setting' of your project folder. This file contains only settings of the last debug session and is automatically created again after starting a new debug-session.</p>

No. E28	C-SPY Driver for 'MINICUBE': Wrong display of main clock source of QB-78K0MINI-EE
	<p><u>Details</u></p> <p>In the Hardware Setup Window always the System Clock is displayed as main clock source. If an oscillator is mounted at the internal socket CLK1, clock board should be displayed as main clock source.</p> <p>This is only a display problem, if an oscillator is mounted at the internal socket this clock is used as main clock.</p> <p><u>Workaround</u></p> <p>The issue is fixed in version V4.50a and later.</p>

No. E29	C-SPY Driver for 'IE-78K': C-SPY fatal error in case of illegal SFR access
	<p><u>Details</u></p> <p>In case of using the C-SPY debugger and the IE-78K-driver any illegal SFR access causes a fatal C-SPY error.</p> <p><u>Workaround</u></p> <p>The issue is fixed in version V4.50a and later.</p>

<p>No. E30</p>	<p>C-SPY Driver for 78K0R 'IECUBE' or 'MINICUBE': Fatal error after selecting 'SFR' in disassembly window</p>
	<p><u>Details</u></p> <p>If in the disassemble window the memory area 'SFR' is selected, the debugger generates a FATAL ERROR: unknown exception in driver (#M1) and the debug session is closed.</p> <p><u>Workaround</u></p> <p>Don't select the memory area 'SFR' in the disassemble window, because code execution is not possible in this area. The issue is fixed in version V4.50a and later.</p>
<p>No. E31</p>	<p>C-SPY Driver for 78K0R 'IECUBE' or 'MINICUBE': Memory read access by macro is blocked</p>
	<p><u>Details</u></p> <p>Memory read is blocked when executing a macro from a breakpoint during execution.</p> <p><u>Workaround</u></p> <p>Please update to version V4.40c or later.</p>
<p>No. E32</p>	<p>Code Coverage information is incomplete in case of using banked memory systems.</p>
	<p><u>Details</u></p> <p>If an application uses banked memory, the Code Coverage information is incomplete.</p> <p><u>Workaround</u></p> <p>Please update to version V4.40c or later.</p>
<p>No. E33</p>	<p>C-SPY Driver for 78K0R 'MINICUBE': The input field for the main clock source allows only selecting a value from a predefined list.</p>
	<p><u>Details</u></p> <p>The input field for the main clock source allows only selecting a value from a predefined list. Therefore it is not possible to enter the correct frequency, if an external clock of a frequency not listed is used. The selection of a different frequency causes a C-SPY fatal error after switching to the external clock.</p> <p><u>Workaround</u></p> <p>The problem will be fixed in version V4.50a or later. In case of any urgent request, please contact NEC Electronics Tool Support Team ('software_support@eu.necel.com').</p>

<p>No. E34</p>	<p>If the same name is used for a data-object and for a data-type, this data-object can not be displayed in the Watch Window.</p>
	<p><u>Details</u></p> <p>If the same name is used for a data-object and for a data-type, this data-object can not be displayed in the Watch Window. After adding the data-object to the Watch window, an error message is displayed instead of the value:</p> <pre>[syntax error, unexpected TYPE_NAME] column 1</pre> <p>Example</p> <pre>struct same_name { struct same_name * next; unsigned int dummy1; unsigned int dummy2; }; struct same_name s1; struct same_name *same_name;</pre> <p><u>Workaround</u></p> <ol style="list-style-type: none"> 1) Use different names for data-objects and data-types 2) Enter the physical address of the data-object and the corresponding type-cast to the Watch Window instead of the symbolname. Example <code>(struct same_name*) 0xFB00</code> <p>The problem will be fixed in version V4.50a or later.</p>

<p>No. E35</p>	<p>Argument variables can not be used to define a code breakpoint by source location.</p>
	<p><u>Details</u></p> <p>Argument Variables can not be used to define a code breakpoint by source location, e.g. <code>\$PROJ_DIR\$\source\main.c, row 26.</code></p> <p>In case of using argument variables, the error message 'The file does not exist' is displayed although path and filename are correct.</p> <p><u>Workaround</u></p> <p>This issue is listed as an improvement proposal for future versions.</p>

No. E36	C-SPY Driver for 78K0R Simulator: Instruction 'mov memory_location[C],A' simulated incorrectly
---------	---

Details

The instruction 'mov memory_location[C],A' is not simulated correctly. A wrong value is written to memory.

Extract from compiler list file, the incorrectly simulated instruction is marked **red**.

```

      8          for( i=0 ; i < SIZE; i++ ) {
\    000001 F0          CLRB      X
\    000002 EF07          BR        S:??main_0
      9          array[ i ] = 0;
\          ??main_1:
\    000004 60          MOV        A, X
\    000005 72          MOV        C, A
\    000006 F1          CLRB      A
\    000007 28.....    MOV      (array & 0xFFFF) [C], A
     10          }
\    00000A 80          INC        X
\          ??main_0:

```

Workaround

None. The problem will be fixed in version V4.50a.

No. E37

C-SPY Driver for 78K0R IECUBE: OP-Fetch before execution can not be defined

Details

The checkbox 'Before Exec' in Event Definition Dialogue is always disabled. The user can not define an OP-fetch before execution event.

Name	Usage	Acc	ACond	AddrRange	DCond	DSize	DataRange	DataPattern	ECond	ExtDataRange
EventOPF...	Not Used	F	EQ	0x14E

Workaround

None. Please define an OP-fetch event at the previous instruction.

No. E38

C-SPY Driver for TK-78K: Download to memory banks failed


Details

In case of using a 78K0-device of more than 60KB internal ROM or FLASH memory, the download to memory bank fails.

Workaround

None. The problem is fixed in C-SPY Version V4.50b.

No. E39	C-SPY Driver for 78K0R: High Byte of Program Counter (bit16-bit23) is set to 0x00
	<p><u>Details</u> The set-next-statement-command sets the high byte of the Program Counter (bit16-bit23) always to zero. If the set-next-statement-command is used inside a far function, this will corrupt the debug session and a manual reset is necessary. Also a manual change of the Program Counter in the Register Window sets the high byte always to zero. The issue concerns the 78K0R C-SPY driver for IECUBE, MINICUBE, and TK-Interface.</p> <p><u>Workaround</u> None. The problem will be fixed in future C-SPY Version.</p>
No. E40	C-SPY Driver for 78K0R: A file in Intel-Hex- or Motorola-S-Record format can not be downloaded
	<p><u>Details</u> If an Intel-Hex or a Motorola-S-Record file is downloaded instead of debug file the C-SPY debuggers doesn't finish the download and stays at an endless loop. The complete Embedded Workbench has to be closed afterwards</p> <p><u>Workaround</u> None. Please use any NEC programmer (QB-MINI2, PG-FP4) to program intel-hex files. The problem will be fixed in future C-SPY Version.</p>
No. E41	C-SPY Simulator Driver: Wrong mask-flag is used to control an interrupt
	<p><u>Details</u> By mistake a wrong mask flag may be used to control an interrupt.</p> <p>Example:</p> <p>For the microcontroller μPD78F0547 the mask flag TMMKH0 (MK0H_bit.no4) is used to control the interrupt INTTMO instead the correct mask flag TMMK000 (MK0H_bit.no6).</p> <p><u>Workaround</u> None. The problem will be fixed in the next C-SPY Version. In case of an urgent request please contact the NEC software tools support team (software_support@eu.necel.com) and list used microcontroller.</p>
No. E42	C-SPY 78K0 IECUBE Driver: Full trace break doesn't work
	<p><u>Details</u> In case of using a trace size of less than 128KB, a defined full trace break doesn't stop the application.</p> <p><u>Workaround</u> Please use the max. trace size of 128KB.</p>

<p>No. E43</p>	<p>C-SPY 78K0R Simulator Driver: Interrupt simulation only works correct at priority level three.</p>
	<p><u>Details</u> If an interrupt level two to zero (highest) is defined, the interrupt simulation doesn't work correctly. Although the interrupt configuration (mask-flag and general interrupt enable flag) is correct, interrupts at any other level than three are disabled.</p> <p><u>Workaround</u> Please use only priority level three (lowest) until the problem will be fixed in the next version.</p>
<p>No. E44</p>	<p>C-SPY 78K0 MINICUBE2 Driver: Error message about old firmware version</p>
	<p><u>Details</u> After the installation of the update patch CS78KE_V460b the following error message will occur if the firmware-version of the MINICUBE2 is less than V4.06:</p>  <p><u>Workaround</u> The MINICUBE2 firmware V4.06 will be available b/o October 2008. Until then please contact the NEC software tool support team (software_support@eu.necel.com) to receive further information fixing the problem.</p>
<p>No. E45</p>	<p>C-SPY all Drivers: Update Time Watch Window</p>
	<p><u>Details</u> If a larger structure (size of several KB) shall be displayed in the C-Spy Watch Window, the update time can be up to five minutes if the OCD-emulator (e.g. MINICUBE2) is used and up to two minutes if the IECUBE emulator is used.</p> <p><u>Workaround</u> None.</p>


No. E46	C-SPY Simulator Driver: Incorrect Value shown in Live-Watch Window
	<p data-bbox="331 241 416 271"><u>Details</u></p> <p data-bbox="331 304 1469 394">For certain source code when changing a element of a anonymous structure, an incorrect value is shown in the live watch window of the C-SPY simulator; when changing one of the bits, the whole base type value is changed.</p> <pre data-bbox="331 427 810 853">#define TRUE 1 #define FALSE 0 volatile struct { UNSIGNED INT extP0_flag:1; UNSIGNED INT TM00_flag:1; }; void test(void) { extP0_flag = TRUE; extP0_flag = FALSE; TM00_flag = TRUE; TM00_flag = FALSE; }</pre> <p data-bbox="331 909 496 938"><u>Workarounds</u></p> <p data-bbox="331 972 911 1001">Use the Watch Window or use standard bitfields.</p>

No. E47

C-SPY 78K0 MINICUBE Driver: Incorrect System Clock Selection

Details

If no oscillator is mounted on the target hardware and no external oscillator is mounted on the 78K0 MINICUBE2 clock board, three different system clocks (4 MHz, 8 MHz, or 16 MHz) can be provided by MINICUBE2. The selection is done in the C-Spy Hardware Setup Dialogue:



Independent of the selection, the provided system clock is always 4 MHz.

Workaround

Mount an external oscillator on the socket at the 78K0 MINICUBE2 clock board. If this is not acceptable, please contact the NEC NEC software tool support team (software_support@eu.necel.com) for further support.

No. E48	Incorrect Variable Address may be displayed in Event Window or Watch Window
	<p><u>Details</u></p> <p>If a variable with the same name as one of the CPU registers (a, x, b, c, d, e, h, l) is used by an application, the symbol lookup cannot distinguish between variable and register name. The address of the symbol name found first is used, but it is undefined which symbol is found first and therefore a wrong address may be displayed.</p> <p><u>Workaround</u></p> <p>Please avoid using the variable names equal to the 78K register names until the problem is fixed.</p>

<p>No. E49</p>	<p>Stack Initialization in default cstartup-module triggers C-Spy Debugger stack observation</p>
<p><u>Details</u></p> <p>A modified cstartup-module included in the compiler update patch V4.61a, triggers by fault the C-Spy stack-observation. In the modified cstartup-module the stack area is initialized to avoid faulty IECUBE emulator fail safe breaks messages about a read access from uninitialized RAM.</p> <p><u>Workaround</u></p> <p>Please add the cstartup-module source code included in the EW78K (cstrtup.s26, subfolder 78K\src\lib) to your application and change the fill-up value in line 135 from 0x00 to 0xCD.</p> <pre> ;----- ; CSTARTUP source for 78K ; ; This module contains the code executed before the C/C++ "main" ; function is called. ; The code usually must be tailored to suit a specific hardware configuration. ; ; Assembler options: ; ; -D__STANDARD_MODEL__ To assemble for use with compiler standard ; code model. ; ; -D__BANKED_MODEL__ To assemble for use with compiler banked ; code model. ; ; -D__NEAR_MODEL__ To assemble for use with compiler near ; code model. ; ; -D__FAR_MODEL__ To assemble for use with compiler far ; code model. ; ; Linker options: ; ; -D_CODEBANK_REG=0 To link for use with "standard" code model, ; no banked functions. ; ; -D_CODEBANK_REG='addr' To link for use with "banked" code model or ; "standard" code model with banked functions. ; 'addr' = bank switch register address. ;----- ; Copyright (c) 2003-2008 IAR Systems AB. ; \$Revision: 3577 \$;----- ... MOV A, #0xCD ; line 135 change fill-up value from 0x00 to 0xCD ... </pre>	


No. E50 Wrong display of array in C-Spy Watch Window

Details

If an array is displayed in the watch window, not only the correct content is displayed, but also the following addresses until the next string-end-character.

```
#include <stdio.h>
__root unsigned char aa[3]={0x30,0x30,0x30};

unsigned char array1[6] ="Hello";
unsigned char array2[6] ="World";
```



Workaround

None. The issue will be fixed in a future update.

No. E51

C-SPY 78K Simulator Driver: Wrong macro access to 16bit data

Details


If a 16bit variable is accessed by a C-Spy macro triggered by an immediate breakpoint cause by an access to the same variable, the macro access may deliver a wrong result.

```
unsigned short test_cnt_u16=0x1717;

void test (void)
{
    test_cnt_u16 ++;
}
```

C-Spy Macro:

```
log_counter()
{
    __message "Testcounter : ", test_cnt_u16:%d;
}
```



Workaround

Use a software breakpoint to trigger the C-Spy macro. The problem will be fixed in the next update.

No. E52

C-SPY 78K: Displayed floating point value in watch window may be wrong

Details

The displayed value of a floating point variable in the Watch Window may be incorrect.


```
float d1, d2, d3, float_a, float_b, float_c;
```

```
void main( void )
{
    float_a = 0.1;
    float_b = 0.0153;
    float_c = 0.015299999;

    d1 = float_a * float_b;
    d2 = float_a * float_c;
    d3 = d1 * 20.0;

    while(1){}
}
```

The displayed value of 'd1' is wrong, but the application uses the correct value. This can be seen in the calculated value of d3.



Workaround

None. The problem will be fixed in the next update.

(M) Description of Operating Precautions for the Assembler A78K0R

<p>No. F1</p>	<p>RSEG Directives can not be used in Macro Definitions</p>
	<p><u>Details</u></p> <p>The assembler calculates a wrong relative jump-distance if the RSEG directive is used within a macro definition:</p> <p><u>Example</u></p> <pre>myDummyMacro MACRO RSEG CODE NOP ENDM</pre> <p><u>Workaround</u></p> <p>Don't use the RSEG directive in macro definitions. The used code-segment must be defined in the code where the macro is expanded to.</p>
<p>No. F2</p>	<p>It is not possible to use an assembler DEFINE to an external symbol</p>
	<p><u>Details</u></p> <p>In case of using an assembler DEFINE to an external symbol, the linker will generate the following error:</p> <pre>Fatal Error[e20]: Corrupt file. External index out of range in module MODUL2 (C:\....\test.r26)</pre> <p><u>Example</u></p> <pre> EXTERN S2 SYM DEFINE S2</pre> <p><u>Workaround</u></p> <p>None. The assembler version V4.41a or later will generate an error for such cases.</p>

<p>No. F4</p>	<p>EVEN Directive doesn't align Data to even Address.</p>
<p><u>Details</u></p> <p>The EVEN directive aligns to an even address relative to the start module-startaddress of the segment instead of an absolute even address. In case of an odd module-startaddress also all symbols aligned with an even-directive are located at an odd address. In this case a linker error message will be generated for each access to the misaligned variable:</p> <pre>IAR Universal Linker V4.60A/386 Copyright 1987-2006 IAR Systems. All rights reserved.</pre> <p>Error[e18]: Range error, Even value expected File: H:\Data\...\even.asm, Line: 17 Source: MOVW S:integer1, AX Where \$ = test_even + 0x1 [0xA8] in module "even", offset 0x1 in segment part 1, segment CODE What: (integer2 + 2) & 1 [0x1] Allowed range: 0x0 - 0x0 Operand: integer2 [0xfe23] in module even, Offset 0x2 in segment part 0, segment SADDR_Z</p> <p><u>Example</u></p> <pre>RSEG SADDR_Z CharVar1: DS 1 EVEN IntVar1: DS 2</pre> <p><u>Workaround</u></p> <p>Please align the segment-start address to an even address:</p> <pre>RSEG SADDR_Z(1) CharVar1: DS 1 EVEN IntVar1: DS 2</pre>	

No. F5	Automatic Replacement of DBNZ Instruction causes Linker Error Message
	<p><u>Details</u></p> <p>In case of using the 78K0 DBNZ instruction with the 78k0R assembler, the assembler outputs a warning that this instruction is not available and will be replaced by DEC and BNZ instruction. But the automatic replacement causes the following linker error message:</p> <p>Error[e18]: Range error, Limit exceeded</p> <p><u>Example</u></p> <pre>asm_func: push BC DBNZ C,m1 ; is replaced by DEC C and BNZ m1 DBNZ B,m1 ; is replaced by DEC B and BNZ m1 m1: pop BC ret</pre> <p><u>Workaround</u></p> <p>Please use directly the correct instructions:</p> <pre>asm_func: push BC DEC C BNZ m1 DEC B BNZ m1 m1: pop BC ret</pre>

No. F6	Invalid Register in XCH Instruction causes the generation of wrong Op-Code
	<p><u>Details</u></p> <p>In case of using the XCH instruction with two registers, register A (R1) must be the first parameter. If register A (R1) is used as second parameter a wrong op-code is generated instead of displaying error message [Ab0006] illegal register:</p> <p><u>Example</u></p> <pre>asm_func: push AX xch X,A pop AX ret</pre> <p><u>Workaround</u></p> <p>Please use only the correct XCH instruction with register A (R1) as first parameter:</p> <pre>asm_func: push AX xch A,X pop AX ret</pre>

No. F7	Invalid XCH instruction doesn't cause a syntax error
<p><u>Details</u></p> <p>The XCH instruction with two registers requires that the first parameter is the register A (R1). If by mistake register X (R0) is used as first parameter, the assembler doesn't generate an error message, but inserts instead the op-code of the instruction <code>xch A, <register></code>.</p> <p><u>Example</u></p> <pre>asm_func: ... xch X,D ... ret</pre> <p><u>Workaround</u></p> <p>Please use only the correct XCH instruction with register A (R1) as first parameter:</p> <pre>asm_func: ... mov A,D xch A,X mov D,A ... ret</pre>	

No. F8	Wrong Op-Code generated for <i>MOV <register>, SFR-address</i> instruction
<p><u>Details</u></p> <p>In case of using an SFR symbol name or absolute SFR address for a MOV <register> instruction where register was unequal A, the assembler generated wrong opcodes. Independent of the used register, the opcode for MOV A, instruction is generated</p> <p><u>Example</u></p> <pre>asm_func: ... mov X, PM0 ; wrong opcodes generated mov B, 0xFFFF20 ; wrong opcodes generated ... ret</pre> <p><u>Workaround</u></p> <p>Please use the 16bit sfr-address until the problem will be fixed:</p> <pre>asm_func: ... mov X, 0xFF20 mov B, 0xFF20 ... ret</pre>	

No. F9	Illegal MOV instruction is accepted and wrong Op-Code is generated
	<p><u>Details</u></p> <p>The assembler accepts illegal mov instructions from another register than register A (mov <register1>, <register2>) and generates always the op code for the correct instruction mov <register1>,A.</p> <p><u>Example</u></p> <pre>asm_func: ... mov B,C ; illegal instruction, opcode for mov B,A generated mov D,H ; illegal instruction, opcode for mov D,A generated ... ret</pre> <p><u>Workaround</u></p> <p>Please use correct instructions 'mov <reg1>, A' only.</p>

No. F10	Invalid operand of branch instruction causes fatal assembler error
	<p><u>Details</u></p> <p>The usage of an invalid operand for the unconditional branch instruction causes a fatal error of the assembler and an abnormal termination. Additionally the user is asked to send a problem report to Microsoft (only version v4.60a)</p> <p><u>Example</u></p> <pre>asm_func: ... br CS:0xDF00 ; invalid operand ... ret</pre> <p><u>Workaround</u></p> <p>Please use only correct operands described in manual, e.g.</p> <pre>mov CS, #0x0F movw AX, 0xDF00 br AX br F:0xFDF00 br N:0xDF00 br 0x0010</pre>

No. F11	Illegal indirect MOVW instruction is accepted and wrong Op-Code is generated
<p><u>Details</u></p> <p>For the illegal instruction MOVW AX,[BC] the opcode for MOVW, word[BC] is used but the offset address is not entered.</p> <p><u>Example</u></p> <pre> PUBLIC asm_func RSEG CODE:CODE asm_func: MOVW AX,[BC] ; -> illegal instruction, opcode for MOVW ;AX,word[BC] generated, but no offset entered ret </pre> <p><u>Workaround</u></p> <p>Please use correct instruction 'MOVW AX,0x0000[BC]'.</p>	

No. F12	Illegal Op-Code generated if SFR symbol is defined after the usage
<p><u>Details</u></p> <p>The assembler generates an illegal opcode, if a sfr-symbol is defined after the usage. Instead of a three byte instruction (2 byte opcode + 1byte for the low-byte SFR-address) a four byte instruction (2 byte opcode + 2byte address) is generated.</p> <p><u>Example</u></p> <pre> PUBLIC test SFR1 DEFINE 0xFFFF0 RSEG CODE test: MOV1 SFR1.0,CY MOV1 SFR2.0,CY ; illegal opcode generated RET SFR2 DEFINE 0xFFFF1 ret </pre> <p><u>Workaround</u></p> <p>Please make sure that all SFR symbols are defined before using them.</p>	

(N) Description of Operating Precautions for the C/C++ Compiler ICC78K0R

No. G6	Warning [Pe177] generated by fault
	<p><u>Details</u></p> <p>If a variable defined as ‘__root’ is additionally defined as ‘static’, the compiler will generate the warning message [Pe177] by fault:</p> <pre>Warning[Pe177]: variable "test1" was declared but never referenced</pre> <p>The keyword ‘__root’ informs the linker that the variable should be located even it is not referenced. This implies already that a variable might not be used in the module and that this declaration is done on purpose.</p> <p>Example:</p> <pre>static __root __far const char test1= 0x01;</pre> <p><u>Workaround:</u></p> <p>The problem will be fixed in the next major update. So far please use one of the following workarounds:</p> <ol style="list-style-type: none"> 1) Don't define a variable as ‘__root’ and ‘static’ 2) Disable warning [Pe177] for such definitions: <pre>#pragma diag_suppress=Pe177 static __root __far const char test1 = 0x01; #pragma diag_default=Pe177</pre>

No. G7	Fatal error in case of using experimental option –mfc
	<p><u>Details</u></p> <p>If two static functions of the same name exist in modules that are compiled simultaneously by using the currently experimental option –mfc, a fatal error occurs:</p> <p>Internal Error: [CoreUtil/General]: OgModuleLables - label already defined. Fatal error detected, aborting.</p> <p>Example:</p> <pre>source file f1.c: static unsigned char func1 (unsigned char p1) { // code doesn't matter return (1); } source file f1.c: static unsigned int func1 (unsigned int p1) { // code doesn't matter return (1); }</pre> <p><u>Workaround:</u></p> <p>The problem will be fixed in the platform release, when the option –mfc will be officially introduced (V4.4xx, schedule is December 2007)</p>

No. G11	Internal compiler error occurs if a default segment name is used for a user-defined segment.
	<p><u>Details</u></p> <p>In case of using a default segment name of the compiler for user-defined segment of constant data, an internal compiler error occurs after the warning about using a default segment name .</p> <p>Internal error [Front end]: Invalid C99 IL expression kind Fatal error detected aborting.</p> <p>Example:</p> <pre>#pragma location = "CODE" __root const unsigned char counter=23; void test(unsigned char *p1) { *p1=((volatile const unsigned char *)&counter); }</pre> <p><u>Workaround:</u></p> <p>Do not use the compiler default segment names for user-defined segments</p>

No. G12	Wrong access to far and byte-aligned structure
	<p><u>Details</u></p> <p>In case of using the data model near and accessing a 16bit value in a far and byte-aligned structure, the compiler splits the word load in two char loads. During the split it reverts to using the default pointer, in this case near. This causes a read from the wrong location.</p> <p>Example:</p> <pre>#define FAR_ADDRESS 0x030000 #pragma pack(1) typedef struct { unsigned char element1; unsigned short element2; unsigned char element3; } MyStruct; #pragma pack() unsigned short Test1; void test(void) { Test1 = ((MyStruct __far *) FAR_ADDRESS)->element2; } </pre> <p><u>Workaround:</u></p> <p>Please use the far data model or update to version V4.50b</p>

No. G13	Wrong code generated for indirect memory access
	<p><u>Details</u></p> <p>In case of using the data model near wrong code may be generated for an indirect memory access. The instruction 'mov A,[HL+C]' is used instead of 'mov A,[HL+B]'.</p> <p><u>Workaround:</u></p> <p>Please use the far data model.</p>

No. G14

Register-bank selection of interrupt function may be ignoredDetails

In case of using an optimization level higher than 'low' the compiler may ignore the register-bank selection of the user (#pragma bank) for some interrupt functions.

Example:

```
#include <io78f1188_e4.h>
extern void f2 (unsigned char );

typedef enum {
    GPT_1,
    GPT_2
}ENUM1;
typedef enum {
    GPT_3,
    GPT_5
} ENUM2;
typedef struct {
    ENUM1      s1;
    unsigned char s2;
    void*      s3;
}STRUCT1_T;

typedef struct{
    ENUM2      s4;
    unsigned short s5;
} STRUCT2_T;

#pragma bank = 2
__interrupt void isr( void )
{
    unsigned short u16PR0sav, u16PR1sav;
    u16PR0sav = PR00 ;
    u16PR1sav = PR01 ;
    __enable_interrupt();

    if (ptr1[((unsigned char) 0)].s1 == GPT_1) {
        array[((unsigned char) 0)].s4 = GPT_5;
    }
    f2( ((unsigned char) 0) );

    __disable_interrupt();
    PR00 = u16PR0sav;
    PR01 = u16PR1sav;
}

```

Workaround:

Please reduce the optimization level for the interrupt function, if the instruction 'SEL RB2' isn't generated for your interrupt function:

```
#pragma optimize = s 3
#pragma bank = 2
__interrupt void isr( void )
{
    ...
}

```

No. G15	Wrong access to local variable located on stack
<p><u>Details</u></p> <p>In case of using multiple nested if statements (level > 4), multiple accesses to local variables located on the stack, and an optimization level greater than low, wrong code may generated for stack-access at lower if statement levels.</p> <p><u>Workaround:</u></p> <p>Please reduce the optimization level to low for the function showing the problem:</p> <pre>#pragma optimize=low void test (void) { ... }</pre>	

No. G16	Internal Compiler Error may occur if calculation result is zero
<p><u>Details</u></p> <p>Code examples where a calculation result is zero may cause an internal compiler error.</p> <p>Example:</p> <pre>signed int i,k; int test(void) { k=90-(9-i)*10; }</pre> <p><u>Workaround:</u></p> <p>Try to rewrite the arithmetic expression to avoid a zero result:</p> <pre>int test (void) { k=90-(90-10*i); }</pre>	

No. G17	Internal Compiler Error occurs if bit complement and bit-and operation are combined in one command
	<p><u>Details</u></p> <p>If the C command to complement a special functions register bit is combined with a bit and command to mask a single bit and an assignment to an integer variable, an internal error occurs:</p> <p>Internal Error: [CoreUtil/General]: Illegal state</p> <p>Example:</p> <pre>#include <io78F1166_A0.h> unsigned int IntVar; void test(void) { IntVar = ~P0_bit.no0 & 0x01; }</pre> <p><u>Workaround:</u></p> <p>Please split up the operations in separate lines of code.</p> <pre>unsigned int IntVar; void test(void) { IntVar = ~P0_bit.no0; IntVar = IntVar & 0x01; }</pre>

No. G18	Wrong code generated for access to multi-dimensional array
	<p><u>Details</u></p> <p>In a case of using optimization type speed level high, the compiler may generate wrong code for the access of multi-dimensional arrays.</p> <p>Example:</p> <pre>static void test (void) { unsigned short x, y; for (y = 0; y < 8; y++){ for (x = 0; x < 128; x++) { buffer[y][x] = 0x00; } } } void dummy(void) { test(); }</pre> <p><u>Workaround:</u></p> <p>Please reduce the optimization level to medium or use while instead of for loops.</p>

No. G19	Spurious linker warning about type conflict
	<p><u>Details</u></p> <p>The compiler could in some cases (e.g. high level of nested typedef types) emit data type incorrect debug information for typedef types. When linking with XLINK, this could result in a spurious type conflict warning:</p> <pre>Warning[w6]: Type conflict for external/entry "<object-name>", in module file2 against external/entry in module file1; different types</pre> <p>The generated code is correct.</p> <p><u>Workaround:</u></p> <p>Please reduce the level of nested typedef types.</p>

No. G20	Extended EC++: Instantiating a template class may cause an internal error
<p><u>Details</u></p> <p>Instantiating a template class like vector on a function type may result in an internal error</p> <p>Internal Error: [Visit types]: Error type</p> <p>Example:</p> <pre>enum eState { state1, state2}; template <class T, T init> class CEnum { public: CEnum() {m_Value = init; } operator unsigned char () const {return (unsigned char)m_Value; } void operator +=(unsigned char arg) {m_Value = (T)(m_Value + arg) } private: T m_Value; }; static __saddr __no_init CEnum<enum eState, state1> state; void test(void) { state += state2; } </pre> <p><u>Workaround:</u></p> <p>None.</p>	

No. G21	Internal Compiler Error occurs if numeric constant is used as function pointer
<p><u>Details</u></p> <p>If an numeric constant is used as function pointer, an internal compiler error occurs: Internal Error: [Call]: Diagnostics: Illegal Operand</p> <p>Example:</p> <pre>void test(void) { (*(void(*)())0x1000)(); } </pre> <p><u>Workaround:</u></p> <p>Use a variable instead of the numeric constant.</p> <pre>unsigned int address = 0x1000; void test(void) { (*(void(*)())address)(); } </pre>	

No. G22	Fatal Error (Uncontrolled termination) occurs if option <code>-Ohs</code> is used
	<p><u>Details</u></p> <p>If the following sample is compiled by using option <code>-Ohs</code> a fatal error occurs: Fatal Error[c0000005hìø_°a`_"°°_„ìø_^°°_"]: Uncontrolled termination In case of using Version V4.60a and WindowsXP the user is asked to inform Microsoft about this issue.</p> <p>Example:</p> <pre>typedef struct { unsigned char MyByte; }T_MYSTRUCT; extern void func1(unsigned char *, unsigned short , unsigned short); void func2(T_MYSTRUCT *p1, unsigned char p2) { unsigned short local; local = (0x0040) + (p2 * 10); func1((unsigned char*)p1,local,10); } unsigned char test(void) { unsigned char local1=201; unsigned char local2=0; T_MYSTRUCT local3; T_MYSTRUCT *plocal3 = &local3; do { func2(plocal3, local1); if (plocal3->MyByte != 0x00) { local2 ++; } local1++; } while (local1 < 204); return (local2); }</pre> <p><u>Workaround:</u></p> <p>Use either option <code>-Ohm</code> instead of option <code>-Ohs</code> or disable 'code inlining' by option <code>-no_inline</code> if option <code>-Ohs</code> is used</p>

No. G23	MISRA C 2004 Rule 17.4 triggered by mistake
<p><u>Details</u></p> <p>MISRA C rule 17.4 is triggered by mistake for arrays included in structures: Error [Pm152]: array indexing shall only be applied to objects defined as an array type (MISRA C 2004 rule 17.4)</p> <p>Example:</p> <pre>typedef unsigned char uint8; void test(void); void test(void) { struct { uint8 u8Array[4]; } tStruct; tStruct.u8Array[0] = 5u; tStruct.u8Array[1] = tStruct.u8Array[0]; }</pre> <p><u>Workaround:</u></p> <p>Disable rule 17.4 by using the #pragma diag_suppress directive for source lines accessing an array included in a structure:</p> <pre>T typedef unsigned char uint8; void test(void); void test(void) { struct { uint8 u8Array[4]; } tStruct; #pragma diag_suppress = Pm152 tStruct.u8Array[0] = 5u; tStruct.u8Array[1] = tStruct.u8Array[0]; #pragma diag_default = Pm152 }</pre>	

No. G24	DLIB Floating Point Function overwrites SADDR area
<p><u>Details</u></p> <p>Some DLIB floating point functions use the SADDR area 0xFFE20 ... 0xFFE27 without reserving it and therefore may override application data.</p> <p><u>Workarounds:</u></p> <ul style="list-style-type: none"> - reserve the area by a dummy variable unused by the application <pre>__no_init __root char dummy[8] @0xFFE20;</pre> - exclude the area in the segment definition in the XCL-file: <pre>-Z (DATA) SADDR_I, SADDR_Z, SADDR_N=FFE28-FFEDF</pre> 	

No. G25	Misaligned structure access
	<p><u>Details</u></p> <p>In the following sample the compiler generates a misaligned access to a byte-aligned structure. The compiler uses a 16bit-instruction to write the return value of the function although the structure maybe located at an odd address.</p> <p>Example:</p> <pre>typedef struct { unsigned char Value; unsigned char Invers; } TWO_CHAR; extern TWO_CHAR func1 (unsigned char Value); volatile TWO_CHAR result; void test (void) { result = func1 (0xaa); // illegal word access }</pre> <p><u>Workarounds:</u></p> <p>Increase the alignment of the structure manually:</p> <pre>#pragma data_alignment=2 volatile TWO_CHAR result;</pre>

No. G26	Wrong parameter passing of far pointer
	<p><u>Details</u></p> <p>In the following sample the compiler generates wrong code during parameter passing of a far pointer, if an optimization level medium or higher is selected. Instead of the correct segment address (= high byte of 20 bit value), a fixed segment address 0xFxxxx is used.</p> <p>Example:</p> <pre>typedef struct { const unsigned char __far* StartAdr; const unsigned char __far* EndAdr; } AREA1; extern const unsigned char array[2][2048]; extern unsigned char func1(const unsigned char __far*, const unsigned char __far*); const AREA1 s2[2] = { { &array[0][0], &array[0][2047] }, { &array[1][0], &array[1][2047] } }; unsigned char result; void test (void) { while(1) { result = func1 (s2[0].StartAdr, s2[1].EndAdr); } }</pre> <p><u>Workarounds:</u></p> <p>Use the optimization level low for the interested function:</p> <pre>#pragma optimize = low void test (void) { ... }</pre>

No. G27	Missing Warning about change of sign due to integer conversion
	<p>If the sign of a constant given in hexadecimal or octal format is changed due to an integer conversion, the compiler doesn't generate a warning (Pe068).</p> <pre>short test (void) { return (0x8000); }</pre> <p><u>Workaround:</u></p> <p>Use the decimal format:</p> <pre>short workaround (void) { return (32768); }</pre> <p>From the next compiler version onwards a remark will be generated if the sign of a constant given in hexadecimal or octal format is changed due to an integer conversion. As result the behavior will be the same for constants given in decimal and hexadecimal format.</p>

No. G28	Delayed insertion of DI instruction
	<p>If the optimization level 'high speed' is used, the insertion of a DI instruction may be delayed, so that the instructions of a following 'if'-condition are execution before the interrupt was disabled.</p> <pre>#include <intrinsics.h> typedef struct { unsigned char e0; unsigned char e1; } T_s1; extern void func1 (volatile T_s1*) ; extern void func2 (volatile T_s1*) ; volatile unsigned char var1; volatile T_s1 *var2; volatile T_s1 *var3; void test(void) { if (var1 >= 3) { __disable_interrupt(); if (var2) { func1(var2); } if (var3) { func2(var3); } __enable_interrupt(); } }</pre> <p><u>Workarounds:</u></p> <p>1) use the inline assembler instead of the intrinsic functions:</p> <pre>void test(void) { if (var1 >= 3) { asm("DI"); if (var2) { func1(var2); } if (var3) { func2(var3); } __enable_interrupt(); } }</pre> <p>2) use a different optimization setting (e.g. medium or high size)</p>

No. G29	Misaligned 16bit-access
	<p>Although the compiler option ‘<code>--disable_data_alignment</code>’ is set, the compiler uses a word instruction to increment a 16bit variable.</p> <pre>unsigned short count; // located at odd address void test(void) { count++; }</pre> <p><u>Workarounds:</u></p> <p>1) don't use the compiler option ‘<code>--disable_data_alignment</code>’ (recommended) 2) use the <code>#pragma data_alignment</code> directive to force that the 16bit value is located at an even address:</p> <pre>#pragma data_alignment=2 unsigned short count; // force location at even address, even if // option --disable_data_alignment is set #pragma data_alignment=1</pre>

(O) Valid Specification

Item	Date published	Document No.	Document Title
1	March 2008	UEW-7	78K IAR Embedded Workbench® IDE User Guide
2	May 2006	C78K-2	78K IAR C/C++ Compiler Reference Guide
3	May 2006	A78K-2	78K IAR Assembler Reference Guide
4	May 2005	M78K-2	78K IAR Embedded Workbench Migration Guide
5	February 2008	CS78KHW-3	78K C-SPY Hardware Debugger Systems Guide
6	December 2007	XLINK-461A	IAR Linker and Library Tools Reference Guide
7	February 2008	EWMISRAC1998-3	IAR Embedded Workbench MISRA C 1998 Reference Guide
8	March 2008	EWMISRAC2004-1	IAR Embedded Workbench MISRA C 2004 Reference Guide

(P) Revision

Edition	Date published	Document No.	Comment
1	05-07-2004	CESCN0004V10	First release.
2	26-10-2004	CESCN0004V11	Items A1 , A2 , C2, C3, D1 added
3	06-12-2004	CESCN0004V12	Items A3 , A4 , A5 , B4 , C4 added, EW78K version V4.20a
4	17-01-2005	CESCN0004V13	Items C5 , D2, E1 added
5	11-02-2005	CESCN0004V14	Items C6, C7, C8 added
6	07-03-2005	CESCN0004V15	Items C9, C10 added
7	08-04-2005	CESCN0004V16	Items C11, D3 , D4, D5, D6 added
8	20-04-2005	CESCN0004V17	Item C12 added
9	10-05-2005	CESCN0004V18	Item C13 added
10	27-05-2005	CESCN0004V19	Items C14, E2 added
11	01-06-2005	CESCN0004V20	Items C15, C16 added
12	22-07-2005	CESCN0004V21	Items C17, B2 , D7, E3 added, EW78K version V4.30a
13	18-08-2005	CESCN0004V22	Items C18, C19, D8 , D9 , D10 , E4 added
14	02-09-2005	CESCN0004V23	Items C20, C21, C22 added
15	13-09-2005	CESCN0004V24	Patch Update for Compiler V4.30c and Debugger V4.30b
16	13-10-2005	CESCN0004V25	Items D11, E5, E6 , E7 added
17	26-10-2005	CESCN0004V26	Items E8, E9 added
18	14-11-2005	CESCN0004V27	Items E10, E11, E12, E13 added, Patch Update for C-SPY Debugger V4.30d
19	01-12-2005	CESCN0004V28	Items E14, E15, E16 added
20	15-12-2005	CESCN0004V29	Patch Update for C-SPY Debugger V4.30e
21	13-01-2006	CESCN0004V30	Item E17 added
22	26-01-2006	CESCN0004V31	Items C23, C24 added

Operating Precautions for EW78K-xxxx-EE

Edition	Date published	Document No.	Comment
23	02-03-2006	CESCN0004V32	Items C25, E18 added
24	13-03-2006	CESCN0004V33	Items C26, E19 , E20 added
25	15-03-2006	CESCN0004V34	Correction of table (C)
26	03-04-2006	CESCN0004V35	Items C27, E21 , E22 added
27	13-04-2006	CESCN0004V36	Items A6 , E23 added
28	09-06-2006	CESCN0004V37	Item C25 updated, items B3 , C28, C29 added
29	11-07-2006	CESCN0004V38	Item C30 added, EW78K version V4.40a
30	20-07-2006	CESCN0004V39	Items A7 , C31 , C32 , G1 , G2 added
31	04-08-2006	CESCN0004V40	Items A8 , A9 , B4 , B5 , F3 , F4 added
32	01-09-2006	CESCN0004V41	Items B4 , A9 , F3 updated, items C33 , C34 , D12 , D13 added
33	07-09-2006	CESCN0004V42	Items D12 , D13 updated
34	06-10-2006	U18447EE1V0IF00	Items C35 , C36 , D14, E24 , G3 , G4 added Items D12 , D13 updated Items C1, C2, C3, C7, C8, D2 removed Patch Update for compiler ICC78K and ICC78K0R version V4.40b and for linker XLINK version 4.60c new NEC Electronics world-wide document number
35	23-10-2006	U18447EE2V0IF00	Items D15 , E25 , E26 , G5 added
36	03-11-2006	U18447EE3V0IF00	Items C37 , E27 , E28 , E29 , G6 added
37	17-11-2006	U18447EE3V1IF00	Items D16 , E30 added
38	23-11-2006	U18447EE3V2IF00	Items E31 , E32 added, patch update for C-SPY V4.40c
39	15-12-2006	U18447EE3V3IF00	Items C38 , G7 , E33 added
40	02-02-2007	U18447EE3V4IF00	Items E34 , E35 , F5 , F6 , added
41	27-02-2007	U18447EE3V5IF00	Items C39 , C40 , G8 , G9 added
42	09-03-2007	U18447EE3V6IF00	Item E36 added
43	14-05-2007	U18447EE3V7IF00	EW78K version V4.50a Items C4, C6, C9, C10, C11, C12, C13, C14, C15, C16, C17, E1 removed Items C41 , D17 , D18 , G10 added
44	18-06-2007	U18447EE3V8IF00	Items C42 , C43 , G11 , F7 added, update of disclaimer, update of valid specification table
45	22-06-2007	U18447EE3V9IF00	Items G12 , E37 added Items D1, D4, D5, D6 removed Linker update V4.60i
46	09-07-2007	U18447EE4V0IF00	Compiler update V4.50b, C-SPY update TK78K V4.50b Item E38 added
47	01-08-2007	U18447EE4V1IF00	Items E39 , G13 added
48	27-08-2007	U18447EE4V2IF00	Items C44 , G14 added
49	28-09-2007	U18447EE4V3IF00	Items E40 , G15 added
50	26-10-2007	U18447EE4V4IF00	Compiler update V4.50c Item E40 updated, Items A10 , C45 , G16 added
51	05-11-2007	U18447EE4V5IF00	Item C46 added
52	22-11-2007	U18447EE4V6IF00	Item E41 added
53	06-12-2007	U18447EE4V7IF00	Items C47 , G17 added
54	15-01-2008	U18447EE4V8IF00	Items C48 , G18 added

Operating Precautions for EW78K-xxxx-EE

Edition	Date published	Document No.	Comment
55	28-01-2008	U18447EE4V9IF00	Item C49 added
56	11-02-2008	U18447EE5V0IF00	Items C50 , G19 added
57	07-03-2008	U18447EE5V1IF00	Items C51 , E42 , G20 added
58	17-04-2008	U18447EE5V2IF00	Items C52 , G21 , F8 added
59	05-05-2008	U18447EE5V3IF00	Items C53 , D20 added
60	21-05-2008	U18447EE5V4IF00	Items C18-C28, C30, D7, E3,E4, E7, E10-E12 removed Embedded Workbench update EW78K V4.60a Item D20 corrected
61	12-06-2008	U18447EE5V5IF00	Item D21 , F9 added
62	09-07-2008	U18447EE5V6IF00	Items C54 , G22 added, Items E8, E13, E15, E16 removed C-SPY Update V4.60b (support of new 78K0R/lx3 series)
63	17-07-2008	U18447EE5V7IF00	Items E43 , E44 , F10 added
64	22-08-2008	U18447EE5V8IF00	Item A11 added, linker update V4.61h
65	15-09-2008	U18447EE5V9IF00	Items C55 , C56 , C57 , E45 , G23 added
66	21-10-2008	U18447EE6V0IF00	Items C58 , E46 , E47 added
67	15-12-2008	U18447EE6V1IF00	Assembler and compiler update V4.61a, Item C58 corrected, Items G1, G2, G3,G4 removed Item A12 , A13 , G24 added
68	19-01-2009	U18447EE6V2IF00	Items D22 , E48 , G25 added
69	28-01-2009	U18447EE6V3IF00	Items C59 , E49 , G26 added
70	13-02-2009	U18447EE6V4IF00	Items F11 , C60 added
71	02-03-2009	U18447EE6V5IF00	Items A14 , E50 , F12 added
72	09-03-2009	U18447EE6V6IF00	Items D23 , D24 added, linker update V4.61l Items D8, D9, D10, D11, D20 removed
73	04-05-2009	U18447EE6V7IF00	Items C61 , E51 , G27 added
74	08-05-2009	U18447EE6V8IF00	Item G28 added
75	20-05-2009	U18447EE6V9IF00	Item G29 added
76	02-07-2009	U18447EE6VAIF00	Update EW78K V4.62a, Items A15 , E52 added, Items A1, A3, B2, B4, C31...C36, C40, C41, E2, E5, E6, E9, E14, E17... E23, F3, G5, G8...G10 removed
77	07-07-09	U18447EE6VBIF00	Item C62 added, Compiler patch icc78K V4.50e added