



NOTE:
When MIC is not used, the MICBIAS should be
disable in the register settings.

NOTE:
WM8978 must be capless mdoe.
JD: Headphone insert detect
signal is high.



